



SESSION 1 : Basic of Geotechnical Forensic Engineering : Myths and Common Problems in

Ir. Liew Shaw Shong



Content

- Introduction
 - *What is Forensic Engineering?.*
- Frameworks
 - *Approaches for Forensic Engineering.*
- Common Problems & Myths
 - *Issues related to Forensic Engineering.*
- Role of Geotechnical Engineer
 - *Methodology and Approaches*
- Conclusions
 - *Summary of messages to do quality Forensic Engineering*



Introduction

- What is forensic engineering?
- To find out reasons of non-compliance performance (SLS & ULS) of products and the causation (contributory and triggering factors) of undesired incident
- Purposes :
 - *To prevent recurrence and improve reliability & durability of product*
 - *To attribute responsibility and damage recovery (litigation)*
 - *To remedy failure/distress based on root cause*
- Locard's exchange principle : "Every contact leaves a trace"




Frameworks

- Desktop study
- Data collection (collecting evidences)
 - *Incident scene inspection*
 - *Interview with Eye-witness & Specimen collection*
 - *Measurements & Monitoring Data*
- Developing chronological events
- Examine cause-and-effect
- Developing model and failure analysis
 - *Fault Tree Analysis (FTA) – Deductive*
 - *Failure Mode and Effects Analysis (FMEA) & Criticality Analysis (CA) – Inductive*
- Experiments & laboratory tests


Failure Analysis

- Evolved from Reliability Engineering (military), Safety and QA/QC Engineering (but with perspective of post failure review. i.e. a re-run)
- FTA (Backward logic)



Failure Analysis

- FMEA (Forward logic)
 - *Functional (Design Requirements)*
 - *Design (ULS, SLS and Material Specifications)*
 - *Process (Method of Statement & Construction)*





Common Problems & Myths

Common Problems:

- *Inaccessibility to the incident site*
- *Timing between incident occurrence and commission of investigation (Destroy of Evidences)*
- *Incorporative attitudes of involving parties*
- *Release of critical information (information on design, construction records, monitoring results, maintenance and operation)*
- *Conflicting data and facts*
- *Representativeness of interpreted information*
- *Establishment of event sequences*




Common Problems & Myths

Myths:

- *Overly simple postulation of potential mechanisms*
- *Fundamentals of mechanics & kinematic movement traces*
- *Matching of performance data*
- *Cherry picking of facts to favourably suit perceptive failure scenarios*
- *Uniqueness of cause-and-effect relationship*
- *Soundness of evidences collected or implied*
- *Compliance of design codes, work statement & material specifications*

ROLE OF GEOTECHNICAL ENGINEER



- **Geotechnical engineer** in Malaysia is ambiguously regarded as "Geologist" in the public perception.
- Geotechnical engineer is a qualified civil engineer registered with **Board of Engineers Malaysia** as either graduate engineer or professional engineer having relevant and competent experience in geotechnical works
 - ability to plan ground investigation & characterise ground conditions for engineering processes
 - identify & assess the potential geo-hazards and the possible ground borne interaction to proposed structures
 - offer feasible engineering design solutions to ensure safety & satisfactory performance of the end product of the engineering works including its surrounding

9

WHY APPOINT GEOTECHNICAL ENGINEER?

Why Geotechnical Engineer?

Geotechnical engineer as an underwriter for risk assessment.

GI as tools for Geotechnical Engineer

It is regard as necessary, but not a rewarding expense. (Uncertainty, sufficiently accurate design options for Cost & Benefit study)

What Risk in Ground & its Consequence ?

Ground Variability & Geo-hazards.
Financial Viability & Cost Overrun (Construction & Operation).



"My design saves the cost of a site investigation ..."

10

GEOLOGY (PENINSULAR MALAYSIA)





13

RISK ASSESSMENT




14





17



18




Engineering Judgement


- **Definition** : The operation of the mind, involving “**comparison**” and “**discrimination**” by which knowledge of values and relations is mentally formulated. (*Webster’s New Collegiate Dictionary*)
- **Recognition** : **Engineering judgement** as an acceptable engineering practice



Engineering Judgement





HOLISTIC APPROACH



21


WORKSCOPE OF GEOTECHNICAL ENGINEERING

Scope



22


WORKSCOPE OF GEOTECHNICAL ENGINEERING



Potential Scope of Geotechnical Engineering (modified from Atkinson, 2006)

23

GEOTECHNICAL WORKS



24

GEOTECHNICAL WORKS



25

GEOTECHNICAL WORKS



26

GEO-ENVIRONMENT




27

UNCONTROLLED DUMP



28



Weathering Profile

- Deviation of material classification between borehole and excavation
(Claim issue – Soil or Rock ?)

30

GEOLOGICAL




Difficulties in Identification of Complex Geological Settings



Difficulties in Identification of Complex Geological Settings




FAILURES



DELIVERABLES



35



36

SUPERVISION



Babylonian King, Hammurabi (1792-1750BC) - "eye for an eye" method :

- If a builder builds a house for a man and does not make its construction firm and the house which he has built collapses and causes the death of the owner of house – the builder shall be put to death
- If it causes the death of the son of the owner of the house – the son of that builder shall be put to death
- If it causes the death of a slave of the owner of the house – he shall give to the owner of the house a slave of equal value
- If it destroys a property, he shall restore whatever it destroyed, and because he did not make the house which he built firm and it collapsed, he shall rebuild the house which collapsed at his own expense
- If a builder builds a house for a man and does not make its construction meet the requirements and a wall fall in, that builder shall strengthen the wall at his own expense

- Translated by R.F. Harper

37

SUPERVISION

CODE CIVIL DES FRANÇAIS.

TITRE PRÉLIMINAIRE.

DE LA PUBLICATION, DES EFFETS
ET DE L'APPLICATION DES LOIS
EN GÉNÉRAL.

ARTICLE 1^{er}

Les lois sont exécutoires dans tout le territoire français,
en vertu de la promulgation qui en est faite par le PREMIER
CONSEIL.
Elles sont exécutées dans chaque partie de la Républi-
que, du moment où la promulgation en a été faite.
La promulgation faite par le PREMIER CONSEIL sera répu-
tée comme dans le département où siège le Gouvernement,
ou tout autre celui de la promulgation, en deux heures
des autres départements, après l'expiration du même délai,
augmenté d'autant de jours qu'il y aura de fois des septen-
naires [c'est-à-dire vingt-trois semaines] entre la ville où la

Napoleonic Code (1804) :

- If a structure had a loss of serviceability within 10 years of its completion, due to poor workmanship or foundation failure, then the builder would be sent to prison.



38

|| Innovation



39


|| Forensic Engineering

- To learn the **consequence** of **ignorance**, **design overlooks** or **overconfidence** of an engineering works.
- A complete investigative cycle looking for factual evidences and rational reasoning of the **causation** out of the probable possibilities and **sequence** of the failure events.
- Very valuable lesson learnt & unforgettable experience to prevent similar recurrence.
- Common problems faced in forensic investigation : **overwhelming** of either **irrelevant or conflicting information**; **untimely access** to the scene for gathering **first hand information**.
- For problems with complex action-soil-structure interaction, it is essential to figure out the moment of which certain components in the system reach their corresponding ultimate limit state condition leading to the unacceptable performance.
- Forensic investigation is often tied up with legal proceeding to recover and apportion the **damage** and **responsibility** to the parties at fault. For complicated cases, the loss adjuster will recommend engagement of geotechnical specialist consultant to investigate the causation and determine reasonableness of the proposed remedial solution by the insured.
- Common findings in geotechnical forensic investigation by the author are as follow:
 - Poor understanding of ground conditions due to inadequate ground investigation and laboratory testing,
 - Technical deficiencies, likes design errors, mistakes in specification or construction/sho p drawings,
 - Non-compliance on materials, approved method statement due to lack of supervision,
 - Lack of maintenance,
 - Improper usage of structure during construction stage by builder or operation stage by owner,
 - Vibration and erosion.

In most cases, the first three factors account for the failures.


40

Examples of Interfacing Issues with Other Project Stakeholders





41

Examples of Interfacing Issues with Other Project Stakeholders



42



Roles of Engineers and Geologists

| | Engineering Geologists | Geotechnical Engineers |
|---|--|---|
| 1 | Provide regional geological setting & potential geohazards | Covers all geotechnical aspects of a project |
| 2 | Detailed study of site geology and produce specific geological models and maps | Planning and implementing site investigations to obtain design parameters for engineering analysis |
| 3 | Engineering geology such as geological formations, slope conditions, highlight potential geological constrains and problematic areas and materials | Carrying out detailed engineering analysis for possible failure mechanism, suitable engineering solutions |
| 4 | Engineering geological assessments provide to engineer, including during construction, if required | Undertaking detailed engineering designs of all geotechnical components, supervision and advising on monitoring and maintenance |


Example 1: Slope Strengthening Design



Example 1: Slope Strengthening Design



Example 2: Slope Failure Investigation



Example 2: Slope Failure Investigation



Summary


- Geologists identify geological constraints and forewarn the Engineers of such constraints.
- The Engineers would then decide on the proper course of actions to be taken to counter such constraints with engineering solution to ensure public safety.

Complexity of Rock Mass

Properties

- Properties of rock mass strength (slope & excavation design)
- Empiricism requiring judgement (involving subjectivity)
- Information normally only available during construction, not design stage

$$\sigma_1' = \sigma_3' + \sigma_u \left[m_b \left(\frac{\sigma_3'}{\sigma_u} \right) + s \right]^a$$



Communication Problem

We are connecting the bridge deck at the same level successfully!



Summary of Geotechnical Engineer's Role

- Define the role of geotechnical engineering at various project cycles (project inception, investigation, assessment, design, construction stage till maintenance after completion),
- Highlight potential value adding process by geotechnical engineer,
- Lesson learnt from forensic investigation minimize serious mistakes & avoid recurrence,
- Problems encountered, solution exploration & innovation achieved in some of the projects,
- Interfacing problems with other project stakeholders & highlights for future improvements with better mutual understanding,
- Case histories demonstrate the important role and value of geotechnical engineer in dealing with the uncertainties in the ground.

53

Conclusions

- Application of forensic principles in geotechnical investigation
- Difficulties encountered and ways to overcome
- Role of Geotechnical Engineer & Geologist
- Professional responsibility to reveal truth of the causation factors, failure mechanism, effects and consequences for lessons learnt



Thank You



SESSION 2 : ROLES OF GEOTECHNICAL INVESTIGATION

Ir. Liew Shaw Shong



1

Introduction

Scope



- **Site Investigation**
 - Information on Hydrology, Meteorology, Environment, Natural Resources, Activities & Topography
- **Ground Investigation**
 - Information on Ground & Groundwater conditions
- **Monitoring**
 - Time dependent changes in ground movements, groundwater fluctuation & movements

2

Introduction

Purpose



Introduction

Project Cycle

Ground Investigation

Common Problems & Trend

Conclusion



Why doing GI? Why Geotechnical Engineer? What Risk & Consequence

Why doing GI?

It is regarded as necessary, but not a rewarding expense. (Uncertainty, sufficiently accurate design options for Cost & Benefit study)



Why Geotechnical Engineer?

Geotechnical engineer as an underwriter for risk assessment.



What Risk in Ground & its Consequence ?

Ground Variability & Geo-hazards.
Financial Viability & Cost Overrun (Construction & Operation).



"My design saves the cost of a site investigation ..."

5

WITHOUT SI, GROUND IS AN HAZARD

Sink hole triggers dramatic Florida viaduct collapse

SITE INVESTIGATIONS failed to pick up a sink hole which caused a motorway viaduct to collapse in Tampa, Florida, last month.

Ground investigations involved borehole probes to 3.5m below the base of the 19.5m foundations for each of the viaduct's 212 piers.

Project client Tampa-Hillborough Expressway Authority said this was double normal requirements.

A 6m high pier for the 10km long highway sank suddenly into the ground on 13 April during construction of a glued segmental deck span.

The reinforced concrete pier almost completely disappeared.



The collapse was slow enough for workers to get clear, although two were taken to hospital. The busy Lee Roy Selman Crosstown Expressway which runs beneath the viaduct was closed until traffic could be redirected.

Cause of the collapse is thought to be a limestone sink

hole, more than 30m below the site. A spokeswoman for the Authority said Florida was largely underlain by limestone and sink holes were prevalent. It was impossible to determine the location of every one.

Ground investigation was by Dames & Moore, subcontractor to the Authority's general

engineering consultant URS. Additional input was made by Williams Earth Science.

Ground radar and seismic probing may now be used to check the remaining pier locations for the highway. The existing 160 piers should be okay said the Authority spokeswoman.

"The pier sank when the launching truss for assembling the 16 segment precast span was fully loaded which means it had half a 700,000lb (320t) load on it," she said. Existing piers have already received this de facto load test.

The \$310M project, due for completion next year, will create an additional three-lanes, 6m above a busy existing commuter route. Traffic flow will reverse between morning and night.

Designer for the elevated structure is the Flagg Engineering Group and contractor PCL Civil Constructors from Canada.

Source :http://www.sptimes.com/2004/04/16/Tampabay/At_site_of_collapse_.shtml

6

WITHOUT SI, GROUND IS AN HAZARD

Light saves man in sinkhole scare

IPOH: When Lee Pek Sang, 84, got up to answer nature's call at 3am yesterday, he realised something was amiss.

The toilet at his home in Bukit Mertah New Village, was missing — lost to a sinkhole.

The sinkhole, measuring 2.44m by 4.57m, was the 21st that had occurred in the area since last October, according to Geological Survey Department officers.

Lee said he would have fallen into the sinkhole if not for the light outside the toilet which was always switched on.

He also said he cannot leave his home because he had nowhere else to go.

The last sinkhole which appeared at the new village next to a cobbler's house on May 16 measured 2m by 8m.

MP for Batu Gajah Yeong Chee Wah will ask to make public the findings on the frequent appearance of sinkholes at the Bukit Merah new village during the Dewan Rakyat sitting in July.

Yeong said the affected villagers have been living in fear since October, adding that some form of remedial action should be taken.

At present, the sinkholes are a threat to 50 houses located side-by-side in three rows in the village.

The village elders when questioned about the occurrence of sinkholes there, said water from a nearby mining pool was drained away underground below the affected houses and could be the main reason for the sinkholes.

The Lahat mines about 500m away from the Bukit Merah New Village is a large and very deep dry mine which has existed for years and has been dubbed the "Grand Canyon of Malaysia" since it could be seen when travelling on the new Ipoh-Lumut outer ring road.



DEEP TROUBLE ... Yeong (standing, left) peering into the sinkhole at what used to be Lee's toilet yesterday. The MP pledges to follow up on the matter at the Dewan Rakyat in July.

7

WITH SI, GROUND CAN BE A HAZARD

DROWNING IN MUD

AN UNNATURAL DISASTER ERUPTS WITH NO END IN SIGHT



Source :National Geographic (Jan 2008) ⁸

WITH SI, GROUND CAN BE A HAZARD

By Andrew Marshall
Photographs by John Dill

By dawn, the tr

to creep into the night
had become a building,
the smallest house he
manages a view in the
town, he is surrounded by
bamboo and limestone, I
and that. "I know the re-
for this." My house was
bamboo last, a place
a landscape of nature
around of his house, a
series of stone-cement
paved paths leading to the
gate of the village.

Later, in Indonesia
one of the more beautiful
and geologic. Various
spaced millions of years
blackening an area of
dark grey limestone.
ground under the sea
and 10,000 feet below
their houses. So far, a
stone, the limestone
differs from the ground
and triggered a series of
events. Indonesia, it
is the underground.

Later, a volcano
Indonesia used the
area the name of the
company for decades
had been mostly covered
up, leaving only a
of mud that contains
Pipes dug into the
stone limestone, it
is done's choice the
bamboo, a city of 2.5
times the mud can
which stones, but
colony mountains,
they could stop the old
game, and modern.

UNDER THE MUD VOLCANO

It began with a burst of steam and a spurt of mud. But the gloopy surge that locals call Lusi soon became a sprawling nightmare. Satellite images (top) show Lusi swallowing more than two square miles in the Porong District. A cross section (right) illustrates what geologist Richard Davies believes caused the disaster.

1. Drillers exploring for gas bored 3,580 feet down, then inserted a steel casing to strengthen the hole.
2. Drilling went deeper without the steel casing. Water and gas filled the hole, and the resulting pressure fractured unprotected rock strata.
3. Hot, high-pressure water was released, probably from the Kujung aquifer.
4. The water raced upward and liquefied masses of mudstone.
5. Mud surged through layers of mudstone and sandstone and broke through the surface.
6. Engineers built dikes in an attempt to contain the mud.
7. Underground, caverns formed and collapsed, causing faults.



Source : National Geographic (Jan 2008) ⁹

Unexpected Blowout of Underground Gas


- Gas pockets at 32m bgl
- Flushing out of sand



GOD CREATION & HUMAN CREATION



■ How GI cost



Consequence



How GI shall be done ?




13




14

Codes & Standards




15

Process Diagram of Ground Investigation




16

Process Diagram of Ground Investigation




17

Stage 1 of GI




18

Stage 2 of GI



19

Stage 3 of GI




"Without Site Investigation, Ground is a Hazard"

20

Desk Study

Information for Desk Study :

- Topographic Maps
- Geological Maps & Memoirs
- Site Histories & Land Use
- Aerial Photographs
- Details of Adjacent Structures & Foundation
- Adjacent & Nearby Ground Investigation



Site Walkover Survey

- Confirm the findings from Desk Study
- Identify additional features & information not captured by Desk Study



|| Site Reconnaissance



23

|| GI Planning

Layout

- Direct influence beneath the proposed structure/works
- Distant Impact from the proposed structure/works

Frequency


- Light structure
- Compact structure (3 ~ 5 points)
- Linear infrastructure (Representation of each geological unit)
- Slope : 3 probing per critical section

Vertical Extent

- Foundation : 10% stress bulb or to competent founding strata
 - Slope : Hard strata or bedrock, not less than overall slope height
- Watch out for boulder, cavity, hard pan, necessary depth for weathering profile


24

Depth of Investigation




Stability Analysis

Foundation Design



Common Problems

- Incomplete Survey Information



|| GI Planning

Sampling

- Reasonable samples in each soil strata and bedrock
- Groundwater samples

In-situ Test

- Advance indication on strength, stiffness, permeability
- Direct testing
- Less sample size effect
- In-situ stress

Laboratory Test

- Sample quality & disturbance
- Late availability of result
- Stress path controlled & effective strength are possible under controlled environment

27

|| GI Planning

Monitoring

- Ground movement (sliding surface, settlement/compression)
- Groundwater Fluctuation
- Appropriate timing & monitoring duration
- Identify potential failure mechanism

Stage of Investigation

- Preferably in three stages (strategically)
- Preliminary GI with contingency provision – Broad overview of ground conditions
- Detailed GI – At critical areas for more information
- GI in Construction/Verification – Areas not covered in previous GI/design modification

Flexibility

- Allow for flexibility of information coverage catering for option exploration

28

Specification

- Objectives (study, design, forensic, construction)
- Type of investigation, mapping & field survey
- Vertical & lateral extent (termination depth)
- Sampling requirements (types, sampling locations & techniques)
- In-situ and laboratory testing requirements (standards)
- Measurement/monitoring requirements (instrument types & frequency)
- Skill level requirements in specialist works & interpretation
- Report format & data presentation

29

Specification

- Work schedule & GI resources planning
- Payments for services, liability, indemnity, insurance cover

30

Boring/Drilling

Recover Sample

- Subsurface stratification/profile
- Material classification & variability
- Laboratory tests

In-situ Testing

- Allow in-situ tests down hole (profiling)
- Direct measurement of ground behaviours

Monitoring

- Allow monitoring instruments installed down hole

31

Direct Method – Boring, Sampling, In-situ & Laboratory Testing

Medical Applications

- Biopsy sampling

Geotechnical Applications

- Boring, Trial Pitting & Sampling

- Thin-walled, Piston Sampler
- Mazier Sampler
- Block Sample

- In-situ Testing

- SPT, MP, CPTu, VST, PMT, DMT, PLT,
- Permeability Test
- Field Density Test

- Laboratory Testing

- Classification Test
- Compressibility Test (Oedometer/Swell)
- Strength Test (UU/UCT/CIU/DS)
- Permeability Test
- Compaction Test
- Chemical Test (pH, Cl, SO₄, Organic Content, Redox, etc)
- Petrography & XRD



32

Indirect Method – Geophysical Survey


Medical Applications

- X-ray, Computer Tomography & MRI
- Ultra-sound

Geotechnical Applications

Geophysical Survey

- Electromagnetic Waves
(*Permeability, Conductivity & Permittivity*)
- Mechanical Wave
(*Attenuation, S-waves & P-waves*)
 - Resistivity Method
 - Microgravity Method
 - Transient Electro-Magnetic Method
 - Ground Penetration Radar
 - Seismic Method




Santamarina, J. C. (2008) - <http://www.elitepco.com.tw/ISC3/images/Keynote-03-Santamarina.pdf>

33

Geophysical Survey

- Merits
 - Lateral variability (probing location)
 - Profiling (sampling & testing)
 - Sectioning (void detection)
 - Material classification
 - Engineering parameters (G_0 & $G_{dynamic}$)
- Problems
 - Over sale/expectation
 - Misunderstanding between engineers, engineering geologists & geophysicists
 - Lack of communication
 - Wrong geophysical technique used
 - Interference/noise




34

Sampler

Split Spoon

Thin-Walled
Piston Sampler
Mazier Sampler
Core Barrel
Wire-line




Sampler

Split Spoon

Thin-Walled

Piston Sampler
Mazier Sampler
Core Barrel
Wire-line



Sampler

Split Spoon


Thin-Walled

Piston Sampler

Mazier Sampler

Core Barrel

Wire-line



37

Sampler

Split Spoon


Thin-Walled

Piston Sampler

Mazier Sampler

Core Barrel


Wire-line



38

Sampler


Split Spoon
Thin-Walled
Piston Sampler
Mazier Sampler
Core Barrel
Wire-line



39

Sampler

Split Spoon
Thin-Walled
Piston Sampler
Mazier Sampler
Core Barrel
Wire-line



40

|| Sample Storage, Handling, Transportation



41

|| Sample Preparation



42

|| Sampling

- Sample Sizes

- Representative mass (particle sizes, fabric, fissures, joints)
- Adequate quantity for testing

- Sample Disturbance

- Stress conditions
- Deformation behaviours
- Moisture content & void
- Chemical characteristics

At Different Stages of SI

| Before | During | After |
|---------------|-----------------------|--------------------|
| Stress relief | Stress relief | Stress relief |
| Swelling | Remoulding | Moisture migration |
| Compaction | Displacement | Extrusion |
| Displacement | Shattering | Moisture loss |
| Base heave | Stone at cutting shoe | Heating |
| Piping | Mixing or segregation | Vibration |
| Caving | Poor recovery | Contamination |

Clayton et al (1982)

43

|| Sample Disturbance

- Poor recovery
 - Longer rest period for sample swelling
 - Slight over-sampling
 - Use of sample retainer
- Sample contamination



Sample Quality Classification

| Sample Quality | Soil Properties | | | | | |
|----------------|-----------------|------------------|---------|----------|-------------|---------------|
| | Classification | Moisture Content | Density | Strength | Deformation | Consolidation |
| Class 1 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Class 2 | ✓ | ✓ | ✓ | ✗ | ✗ | ✗ |
| Class 3 | ✓ | ✓ | ✗ | ✗ | ✗ | ✗ |
| Class 4 | ✓ | ✗ | ✗ | ✗ | ✗ | ✗ |
| Class 5 | ✗ | ✗ | ✗ | ✗ | ✗ | ✗ |

BS 5930 (1981)

45

In-situ Tests



CPT Equipment



- The Seismic Cone Penetration Test (SCPT) is a reliable, cost effective technique to determine the insitu seismic wave velocity.
- Seismic wave velocities give an indication of ground characteristics such as low strain shear modulus and Poisson's ratio.
- Data from the cone penetrometer is used in delineating the strata changes identified by the seismic results.



■ In-Situ Tests

- BS1377 : Part 9
- Suitable for materials with difficulty in sampling
 - Very soft & sensitive clay
 - Sandy & Gravelly soils
 - Weak & Fissured soils
 - Fractured rocks
- Interpretation
 - Empirical
 - Semi-empirical
 - Analytical

■ Applicability of In-situ Tests

| Test | Stress | Strength | | | Stiffness | | | Permeability |
|------------------------------|--------|----------|-------|------------|-----------|-------|-----------|--------------|
| | K_0 | ϕ' | C_u | σ_c | E'/G | E_u | G_{max} | k |
| SPT | | G | C | R | G | C | G | |
| CPT/CPTu | | G | C | | G | | | |
| DMT | G, C | | | | G | | | |
| Borehole PMT | | | C | | G, R | C | | |
| PLT | | | C | | G, R | C | | |
| VST | | | C | | | | | |
| Seismic | | | | | | | G, C, R | |
| SBPMT | G, C | G | C | | G, C | | | |
| Falling/ Rising Head Test | | | | | | | | G |
| Constant Head | | | | | | | | C |
| Packer Test | | | | | | | | R |

Clayton, et al (1995)

G = granular, C = cohesive, R = Rock

49

■ Applicability of In-situ Tests

SUMMARY ON THE COMMON TYPES OF GROUND INVESTIGATION, FIELD TESTS, SAMPLING & LABORATORY TESTS

| Description | Types of Ground Investigation | | | | | | Field Test | | | | | Laboratory Test | | | | | | | |
|--------------------------|-------------------------------|----|----|----|----|----|------------|----|-----|----|----|-----------------|-----|----------|-----|----|-----|-----|------|
| | JP | HA | TP | BH | PZ | GS | SPT | PM | PLT | VS | PW | C | M/C | γ | Con | UU | UCT | CIU | Chem |
| 1) Soft ground treatment | m | m | m | y | y | m | - | - | - | y | m | y | y | y | y | y | y | m | m |
| 2) Shallow foundation | | | | | | | | | | | | | | | | | | | |
| cohesive soil | y | m | m | y | - | - | y | m | y | m | - | y | y | y | y | y | y | m | m |
| non cohesive soil | y | m | m | y | m | - | y | - | y | - | - | y | y | y | - | - | - | - | m |
| 3) Pile Foundation | | | | | | | | | | | | | | | | | | | |
| Fill ground | m | m | m | y | m | m | y | m | - | m | - | y | y | y | y | y | y | - | m |
| Cut ground | - | - | m | y | - | m | y | - | - | - | - | y | y | y | - | - | - | - | m |
| 4) Slope | | | | | | | | | | | | | | | | | | | |
| Cut | - | - | m | y | - | y | y | - | - | - | y | y | y | y | - | y | y | y | - |
| Fill | m | m | m | y | m | m | y | - | - | y | m | y | y | y | y | y | y | y | m |

Legend:



JP : JKR Probe
HA : Hand Auger
TP : Trial Pit
BH : Borehole
PZ : Piezocone
GS : Geophysical Survey

SPT : Standard Penetration Test
PM : Pressuremeter
PLT : Plated Bearing Test
VS : Vane Shear Test
K : Permeability Test
Y : Yes should be done
M : May be added
- : Not relevant/necessary

C : Classification
M/C : Moisture Content
 γ : Unit Weight
Con : Consolidation
UU : Unconsolidated Undrained
UCT : Unconfined Compression
CIU : Triaxial with Pore Water Pressure
Chem : Chemical Test


50

|| In-situ Tests




|| In-situ Tests

Pressuremeter (PMT)



In-situ Tests

Dilatometer (DMT)



53



Geophysics Methods



54

Instrumentation Monitoring

- Inclinometer
- Extensometer
- Rod Settlement Gauge/Marker
- Piezometer
- Observation Well




55

Laboratory Tests




56

Table Top Geotechnical Centrifuge




4000 kg Compact Geotechnical Centrifuge



Vertical orientation for high speed running


A World First - The G-max Modular CgC



Soil Boxes compartmentalise the ring channel for small soil sample testing

Ring Channel for large soil sample testing at high 'G'


Fig 1: Drum Ring Channel with 2 Soil Compartment Boxes



Swing Platforms shown in position at centrifuge rest

Beam Centrifuge operation with effective payload radius 0.2m

Fig 2: Beam Rotor Table with 2 Swinging Soil Strong Boxes



Interpretation
60%



Information
40%

We know what it takes to be a Tiger.

According to our landmark research on leaders at 70 industries, high performers consistently excel at transforming information into action, particularly through the strategic use of IT. For an in-depth look at our study of and experience with high performers, visit [accenture.com/leadership](#)

accenture
High performance. Delivered.


© Accenture LLP • 2007 • All rights reserved

Source : Life Style Magazine - EDGE

Ground Characterisation

Focus of **Geological Model**



59

Geological Mapping

Mapping of :


- | | |
|--|---|
| <ul style="list-style-type: none">- Geological features (Structural settings)- Weathering profile- Outcrop exposure- Seepage conditions | <ul style="list-style-type: none">- Geomorphology- Lithology- Stratification- Sequence of geological actions & history |
|--|---|



60


Ground Characterisation

Focus of **Geotechnical Model**



61

GEOTECHNICAL MODEL



62

COMMON PROBLEMS & TREND

63

General Dilemma of GI Industry

- Lack of pride & appreciation from consultant/client in GI industry.
- Actions done is considered work done!
Poor professionalism.
- Financial survival problem due to competitive rates in uncontrolled environment (cutting corner)
- No appropriate time frame for proper work procedures (shoddy works)
- Shifting of skilled expert to Oil & Gas or other attractive industries

64

|| Poor Planning & Interpretation

- Inadequate investigation coverage vertically & horizontally
- Wrong investigating tools
- No/wrong interpretation
- Poor investigating sequence



5

|| Poor Site Implementation

- Lack of level & coordinates of probing location
- Sample storage, handling, transportation
- Inappropriate equilibrium state in Observation Well & Piezometer

|| Poor In-situ & Laboratory Results

- Lack of equipment calibration
 - Wear & Tear Errors
 - Equipment systematic error (rod friction, electronic signal drift, unsaturated porous tip)
 - Defective sensor
 - Inappropriate testing procedures
- Equipment calibration (Variation of pH Values)
 - Improper sample preparation
 - Inadequate saturation
 - Inappropriate testing rate
 - Inadequate QA/QC in testing processes
 - Inherent sample disturbance before testing

67

|| Poorly Maintained Tools



68

|| Over-confidence in Geophysics

- We detect everything in geophysical data, but indentify almost nothing (**Rich** but **Complex**).
- Not a unique solution in tomographic reconstruction (Indirect method)
- Poor remuneration to land geophysicist as compared to O&G
- Poor investigation specification
- Lack of good interpretative skill (human capital)
- High capital costs in equipment & software investment

69

|| Communication Problem




70

Difficulties in Identification of Complex Geological Settings



Difficulties in Identification of Complex Geological Settings



Weathering Profile

- Deviation of material classification between borehole and excavation
(Claim issue – Soil or Rock ?)




73


Complexity of Rock Mass

- Properties**
 - Rock mass strength (slope & excavation design)
 - Empiricism requiring judgement (involving subjectivity)
 - Information normally only available during construction, not design stage

$$\sigma_1' = \sigma_3' + \sigma_u \left[m_b \left(\frac{\sigma_3'}{\sigma_u} \right) + s \right]^a$$



| Geological Strength Index (GSI) | Rock Mass Strength (σ _u) | Rock Mass Deformation Modulus (E _m) |
|---------------------------------|--------------------------------------|---|
| 10 | 0.001 | 10 |
| 20 | 0.002 | 20 |
| 30 | 0.004 | 30 |
| 40 | 0.008 | 40 |
| 50 | 0.015 | 50 |
| 60 | 0.030 | 60 |
| 70 | 0.060 | 70 |
| 80 | 0.120 | 80 |
| 90 | 0.240 | 90 |



Unexpected Blowout of Underground Gas

- Gas pockets at 32m bgl
- Flushing out of sand



Supervision

- Work compliance & certification
- Document critical information
- Timely on-course instruction (sampling, in-situ testing & termination)
- Checking between field records and reported information

Future Trend - Electronic Data Collection, Transfer & Management

- AGS data transfer format & AGS-M format (monitoring data)

- First Edition in 1992, AGS(1992)
- Second Edition in 1994, AGS(1994)
- Third Edition in 1999

- Advantages :

- Efficient & Simplicity
- Minimised human error
- GI & Monitoring Data Management System
- Record keeping
- Spatial data analysis

<http://www.ags.org.uk/site/datatransfer/intro.cfm>

77

Conclusions

- Nature of GI works & Geotechnical design (**Uncertainties**)
- Role of Geotechnical Engineer, Engineering Geologist & Geophysicist
- Stages of GI works (**Planning, Implementation, Interpretation & Report**)
- Specifications
- Methodology of GI (Merits & Demerits)
 - Fieldworks (Direct/Indirect) + Geological Mapping
 - Laboratory tests
- Common Problems & Future Trend

78

References

- Anon (1999). "Definition of Geotechnical Engineering". *Ground Engineering*, Vol. 32, No. 11, pp. 39.
- BSI (1981). "Code of Practice for Site Investigation, BS 5930". British Standards Institution, London.
- BSI (1981). "Code of Practice for Earthworks, BS 6031". British Standards Institution, London.
- BSI (1986). "Code Practice for Foundation, BS8004". British Standards Institution, London.
- BSI (1990). "British Standard Methods of Test for Soils for Civil Engineering Purposes, BS 1377". British Standards Institution, London.
- CIRCULAR 4/2005 *Engineer's Responsibility for Subsurface Investigation (Generally known as Soil Investigation)*.
- Clayton, C. R. I., Matthews, M. C. & Simons, N. E. (1995). "Site Investigation", Blackwell Science, 2nd edition.
- Gue, S. S. & Tan, Y. C. (2005). "Planning of Subsurface Investigation and Interpretation of Test Results for Geotechnical Design", Sabah Branch, IEM.
- Liew, S. S. (2005). "Common Problems of Site Investigation Works in a Linear Infrastructure Project", IEM-MSIA Seminar on Site Investigation Practice, 9 August 2005, Armada Hotel, Kuala Lumpur.
- MS 2038: 2006 Malaysian Code of Practice for Site Investigation Board of Engineers Malaysia. 2005.
- European Group Subcommittee (1968). "Recommended method of Static and Dynamic Penetration Tests 1965". *Geotechnique*, Vol. 1, No. 1.

79


References

- FHWA (2002). "Subsurface Investigations — Geotechnical Site Characterization". NHI Course No. 132031. Publication No. FHWA NHI-01-031
- GCO (1984). "Geotechnical Manual for Slopes". Geotechnical Control Office, Hong Kong
- GCO (1980). "Geoguide 2 : Guide to Site Investigation, Geotechnical Control Office, Hong Kong
- Gue, S. S. (1985). "Geotechnical Assessment for Hillside Development". *Proceedings of the Symposium on Hillside Development: Engineering Practice and Local By-Laws*, The Institution of Engineers, Malaysia.
- Head, K. H. (1984). "Manual of Soil Laboratory testing".
- Morgenstern, N. R. (2000). "Common Ground". *GeoEng2000*, Vol. 1, pp. 1-20.
- Neoh, C. A. (1995). "Guidelines for Planning Scope of Site Investigation for Road Projects". Public Works Department, Malaysia
- Ooi, T.A. & Ting, W.H. (1975). "The Use of a Light Dynamic Cone Penetrometer in Malaysia". *Proceeding of 4th Southeast Asian Conference on Soil Engineering*, Kuala Lumpur, pp. 3-62, 3-79
- Ting, W.H. (1972). "Subsurface Exploration and Foundation Problems in the Kuala Lumpur Area". *Journal of Institution of Engineers, Malaysia*, Vol. 13, pp. 19-25
- Santamarina, J. C. (2008). "The Geophysical Properties of Soils", 3rd Int. Conf. on Site Characterisation, Keynote Lecture No. 3, Taiwan.
- Site Investigation Steering Group, "Without Site Investigation, Ground is a Hazard", Part 1, Site Investigation in Construction, Thomas Telford Ltd.

80



THANKYOU





SESSION 2: GEOTECHNICAL INSTRUMENTATION

By Ir. Liew Shaw Shong



Course Outline

- 1 Planning, Specification & Contractual Arrangement
- 2 Site Monitoring
- 3 Data Processing / Analysis, Interpretation & Actions
- 4 Common Problems, Applications & Lesson Leant from Case Study





Why Instrumentation?

WHY DO WE NEED INSTRUMENTATION?

It is a useful tool to supplement what we can not identify trend of behaviours & quantify the changes of the crucial parameters affecting the behaviours in the observation.




7 | Texas

COASTAL FURY Hurricane Ike slammed into Galveston (above), and ensuing winds and rainfall drifted up through Texas and north into the Midwest, killing at least 51 people in 10 states and leaving millions without power. Heavy rains caused flooding along the banks of the Mississippi and Missouri rivers. In Texas, thousands crowded into shelters and hotels paid for by the Federal Government, many expecting to stay for weeks. Throughout the region, evacuees waited in long lines for food, water and gas.




Theory .vs. Observation






Benefits of Instrumentation




If you can not get high quality and reliable data, then better don't initiate any instrumentation scheme because it will create more problems than being advantageous.





Pitfalls of Instrumentation



In some cases, instrumentation results may reveal the shortcomings or negligence in the design of the project designer and also those by the work contractor.








Parameters to be Monitored

Types of Measurement



Planning Cycle



Every instrument shall be placed at the site to answer specific question. If no question, then no instrument.



Project Conditions

- **Construction Control** : modify or improve the initial construction sequence or/and method.
- **Remedy** : strengthen the stability, reduce the negative impacts, repair the damage or distresses
- **Notice** : serving notice to project owner, insurance, neighbouring owners, local authorities




Questions to be answered

- **Any Questions related to Performance of the Concerned System**
 - **Deformation of Ground or Structures**
 - **Stress or Strain in Ground or Structure**
 - **Water Pressure Distribution, Flow and Changes**
 - **Thermal, Vibration, Tidal Effects**
 - **Location and magnitude of changes**





What does instrument measure & response?

- Measurement can be either performed on the changes of **CAUSES** (difficult to pick up the changes) or **EFFECTS** (usually too late for response actions).
- Most instruments provide point measurement with dependence on localised characteristics, hence may not represent the problem in larger scale, unless large number of point measurement instruments are installed.




Controlling Mechanisms





Engineering Judgement

- **Definition** : The operation of the mind, involving “**comparison**” and “**discrimination**” by which knowledge of values and relations is mentally formulated. (*Webster’s New Collegiate Dictionary*)
- **Recognition** : **Engineering judgement** as an acceptable engineering practice



The diagram shows the title 'Response Actions' in a blue box. Below the title, there is a list of three actions: 'Construction Control', 'Remedy', and 'Notice'. Each action is preceded by a red square bullet point. The background of the list area features a faint image of a group of people in a meeting.


Response Actions

- **Construction Control** : modify or improve the initial construction sequence or/and method.
- **Remedy** : strengthen the stability, reduce the negative impacts, repair the damage or distresses
- **Notice** : serving notice to project owner, insurance, neighbouring owners, local authorities

Dilemma of Instrumentation




Specification






Contractual Arrangement



Procurement Approach

- **Professional Service**
- **Lowest Bid Tender**
- **Independence**



We're underfunded, but we manage!





Good Practices

- **Instrument Life-Cycle Costs** : Calibration, installation, taking readings, maintenance, data management & interpretation, and decommissioning.
- **Partnership to Instrument Manufacturers/Suppliers**



Good Practices

- **Good QA/QC of Personnel Training, Equipments, Data Management**
- **Dedicated Team & Equipment for Project**
- **Measures of Instrument Protection**
- **Duplicate Instruments for Data Redundancy**





Course Outline

- 1 Planning, Specification & Contractual Arrangement
- 2 **Site Monitoring**
- 3 Data Processing / Analysis, Interpretation & Actions
- 4 Common Problems, Applications & Lesson Learnt from Case Study



Measurement Uncertainty & Reliability






Conformance

- Good conformance of instrument and installation procedures are necessary for measurement of good accuracy.
- Beware of any changes of properties related to parameters to be measured due to presence of instrument



Accuracy & Precision






Measurement Deviation


- **Resolution** : the degree to which the smallest change it can detect in the quantity that it is measuring.
- **Sensitivity** : the smallest absolute amount of change that can be detected by a measurement, usually defined as the ratio between output signal and measured property
- **Linearity** : The amount of error change throughout an instrument's measurement range. Linearity is also the amount of deviation from an instrument's ideal straight-line performance.
- **Hysteresis** : an error caused by when the measured property reverses direction, but there is some finite lag in time for the sensor to respond, creating a different offset error in one direction than in the other
- **Noise** : Random measurement variations by external factors




Linearity & Hysteresis



Non Linearity




Hysteresis



| Types of Errors & Corrective Measures | | |
|---------------------------------------|---|---|
| Type of Error | Sources | Corrective Actions |
| Gross Error | Human mistakes | Care, checking & training |
| Systematic Error | Calibration, hysteresis & non-linearity | Periodic recalibration |
| Conformance Error | Instrument design & installation | Appropriate instrument, improve installation procedures |
| Environmental Error | Weather, temperature, vibration & corrosion | Apply correction with recorded environmental changes & conditioning instrument to ambient environment |
| Observation Error | Variation between observers | Training & automatised data acquisition |
| Sampling Error | Inherent variability & sampling technique | Sufficient instruments |
| Random Error | Noise, friction & environmental effect | Statistical analysis on multiple readings |



| Course Outline | |
|----------------|---|
| 1 | Planning, Specification & Contractual Arrangement |
| 2 | Site Monitoring |
| 3 | Data Processing / Analysis, Interpretation & Actions |
| 4 | Common Problems, Applications & Lesson Learnt from Case Study |





Parameters to be Measured

- **Deformation/Movement**

- Inclinator
- Extensometer
- Ground Movement Marker
- Tiltmeter
- Crackmeter

- **Water/Earth Pressure**

- Piezometer, Observation Well
- Earth Pressure Cell



Parameters & Measurement

- **Load/Stress/Strain**

- Strain Gauges
- Load Cell

- **Thermal**

- Thermal Coupler

- **Flow**

- V-Notch Gauge

- **Vibration**


- Accelerometer





Inclinometer

■ Inclinometer



Inclinometer

Unpredictable & Uncorrectable





Predictable & Correctable



Total Error

Systematic errors can accumulate upward in the cumulative displacement at ground surface (**apparent cumulative displacement**).

$$\text{Total Error} = \epsilon_{\text{Random}} \times \sqrt{(\text{No. of Readings})} + \epsilon_{\text{Systematic}} \times (\text{No. of Readings})$$






Inclinometer

▪ Spiral Probe

- Twisted casings lead to incorrect magnitude of movement in the A and B directions.
- Application :
 - To check orientation of the inclinometer grooves for necessary correction for direction of resultant movement.
 - Readings show movements in unlikely direction
 - Check installation quality
 - Deep casing installation



Inclinometer

▪ Error Detection & Correction :

- Double data redundancy with readings taken in diametrical direction
- 3 to 6m bottom of casing into firm strata for good fixity to provide calibration data
- Deeper readings have highest potential systematic errors : (a) Sensor warming up, (b) Steepest borehole inclination, (c) Further distance from top reference



Inclinometer


- **Tolerance :** Variation of Checksum < 5 to 10 units of Mean Checksum
- **Correction :**
 - If the large variation is localised to one depth, correction can be performed based on mean of other checksum.
 - If the large variation spreads over the entire dataset, it is better to retake the readings.



Inclinometer

▪ Inclinometer (Vertical)






The top photograph shows a wooden wall under construction. A red tank is visible in the background. The bottom photograph shows a completed wall with a blue and white striped marker.




Data Evaluation

▪ Type of Ground Movement



Developed Shear Zone with Drastic Movement Profile



Creeping Slope with Continuous Movement Profile



Data Presentation

▪ Good Practice :

- Use of exaggerated horizontal scale shall be avoided because “errors” are magnified & could be misinterpreted.
- Change plot (incremental deformation) is useful to emphasize the location of deformation zone.



Course Outline

- 1 Planning, Specification & Contractual Arrangement
- 2 Site Monitoring
- 3 Data Processing / Analysis, Interpretation & Actions
- 4 Common Problems, Applications & Lesson Leant from Case Study



Myths in Instrumentation

- **Myth No.1** : Instrumentation can prevent bad thing from occurring.
- **Myth No. 2** : Maintenance free instruments are possible.
- **Myth No. 3** : Geotechnical engineer is not needed to review the instrumentation results if threshold and action plan are available (traffic light system).
- **Myth No. 4** : Instrumentation does not require the input from instrumentation specialist.



Myths in Instrumentation

- **Myth No. 5** : Instrumentation can replace engineering judgement. Everything is fine if instrumentation is in place.
- **Myth No.6** : More instruments and data are better.
- **Myth No. 7** : Instrumentation is costly investment, hence is unnecessary if the design is good.



Common Problems

- **Instrument** : Selection of appropriate instrument fit for the purpose.
- **Contract Arrangement** : Interest party for high quality instrumentation data.
- **Data Quality** : Poor quality data will neither reveal the truth of engineering behaviours nor give correct warning.
- **Data Management** : Keeping raw data is essential for future data reprocessing with new interpretative objectives



Common Problems

- **Data Interpretation** : Screening & filtering of problematic data or uninvited events/factors for a distilled content are deliberately needed.
- **Data Presentation** : Data presentation without connection to records of activities at site is a discounted information for decision making.



Common Problems

- **Review** : Timely review is important to capture indication of distress development & need for instrument maintenance/checking for proper functioning.
- **Loss of Feel** : Sometimes readings given to person who is not taking care of the instruments has no clue to slight variation of the readings, but possible an important indication of adverse effect. (You will not know your baby if you did not take care of him/her.)
- **Threshold Limits** : It is not easy to set a accurate set of threshold limits for multiple parameters controlling the behaviours.
- **Action** : Timely implementation of actions as identified from interpreting instrumentation results.



Advices


■ Paradox :



- Appearance of apparently unmotivated change are often the first sign of distress
- Observations of overall phenomenon become more relevant than “spot” occurrence.



Applications


■ Observation Method (e.g. NATM in Tunnel)









Tunnel & Underground Excavation



Strutting & Excavation






Pile Test Interpretation (using Global Strain Measurement)


- ▶ **Facts on Axially Tested Pile :**
 - ▶ Free standing portion – No friction interference
 - ▶ Embedded portion – Constant or linearly varying shaft friction with depth
 - ▶ Tensile cracking in tensile loading affecting axial stiffness of composite pile section
- ▶ **Factors affecting accuracy of pile instrumentation**
 - ▶ Linearity of load-strain calibration
 - ▶ Pile shaft resistance profile assumed
 - ▶ Instrument locations for pile axial load measurement
 - ▶ Numbers of pile segment movement measurement
 - ▶ Gauge length of strain measurement (global / local strain measurement)
- ▶ **Consequences :**
 - ▶ Interpreted pile axial load at location assigned within the gauge length can be unjustified (unless no interference of shaft friction)




Pile Instrumentation & Interpretation Approaches



Load Transfer of Test Pile



Tensile Pile Test




Case Studies for Dewatering & Seepage Problems




Dewatering

- Case 1 : Investigation of Distress Structure due to Construction Dewatering
- Case 2 : Excavation Stability by Construction Dewatering & Recharge
- Case 3 : Revetment Design Under Seepage


Case 1 - Initial Site Conditions




Case 1 : Dredged Pond in Mining Activities




Case 1 : Deposition of Pond Sediments




Case 1 : Land Reclamation for Development




Case 1 : Housing Construction




Case 1 : Site Preparation Works



Case 1 : Groundwater Pumping in Caissons




Case 1 : Consolidation Ground Settlement




Case 1 : Mechanism of Distresses

- Pumping of Groundwater in Caisson further lower the water pressure at Limestone Interface (Slump Zone) from its original hydrostatic head of Lower Groundwater Regime to probably lowest head of 11m below (average base of Caisson)
- Huge water pressure reduction at Slump zone resulted in remarkable consolidation compression of clayey pond sediments bottom up
- Surface ground settlement is a result of accumulation of consolidation compression within pond sediments
- Surface ground settlement profile led to distortion of building frame and occurrence of cracking


Piezocone Results



Case 1 : Mechanism of Distresses



Case 2 : Dewatering Scheme + Sheet Pile




Case 3 : GEOTECHNICAL REVIEW ON REVETMENT DESIGN

Subsurface Investigation (SI) Works


- Field Works :-
 - 2 nos. of Boreholes
 - 9 nos. of CPTu Tests
 - 6 nos. of Trial Pits
- Field Tests
 - Field CBR Tests
 - Field Density Tests
- Instrumentations
 - 2 nos. of Piezometer on land
 - 1 no. of Piezometer in sea

Soil Improvement Works before Reclamation & Construction of Concrete Block Pavement




SI Layout Plan

Berth A



SI Layout Plan


Berth B




Automatic Water Level Measurement



Groundwater Level Monitoring



Predicted Vs Measured Tide Level



Revetment Design Check

DESTABILIZING FORCES:

F_d = Drag force
 $W_s \sin \alpha$ = Submerged weight parallel to slope

Sliding Force, $F_s = t (\gamma_c - \gamma_w) \sin \alpha$


STABILIZING FORCES:

F_r = Frictional resistance (mat / subgrade)
 $= \mu F_n = \mu (W_s \cos \alpha - F_L)$

Where:


F_n = Normal force
 $W_s \cos \alpha$ = Submerged weight normal to slope
 F_L = Lift force
 μ = Coefficient of static friction

Resisting Force, $F_r = \mu [t (\gamma_c - \gamma_w) \cos \alpha - F_L]$




Reference: EM 1110-2-1614 (1995), Design of Coastal Revetments, Seawalls, and Bulkheads, U.S. Army Corps of Engineers, Washington

**Difference between Tide Level and Groundwater Level
Day 1 - Day 7 (22-08-09 to 28-08-09)**



Revetment Design Check → Not OK

Potential Uplift Forces



Summary of Revetment Design Check

| S/N | Thickness of Incomat (m) | Angle of Inclination (degree) | Uplift force (kPa) | F_s (kPa) | F_r (kPa) | $FOS = F_r / F_s$ | Remarks |
|-----|--------------------------|-------------------------------|--------------------|-------------|-------------|-------------------|--|
| 1 | 0.6 | 22.6 | 0 | 3.228 | 4.475 | 1.386 | Design of Revetment "X" is inadequate where achieved FOS_{max} is less than 1.5 and becomes unstable when subjected to uplift force of greater than 2.5kPa |
| 2 | | | 2.00 | 3.228 | 3.321 | 1.029 | |
| 3 | | | 2.50 | 3.228 | 3.032 | 0.939 | |
| 4 | 0.6 | 0.1 | 8.36 | 0.015 | 0.023 | 1.574 | Max. uplift pressure that can be resisted by 0.6m thick Revetment "X" is 8.36kPa when placed horizontally. |
| 5 | 0.6 | 21.0 | 0 | 3.010 | 4.525 | 1.503 | When assuming allowance for pressure relief has been made on the Revetment "X", the performance of Incomat would be satisfactory if the angle of slope is less than 21 degree. |

Sufficient Pressure Relief (Filter Point and/or Weep Hole) is Important to Safeguard the Performance of Revetment "X" (Grout Filled Mattress) Resting on Inclined Sandfill slope

THANK YOU



Summary of Pile Instrumentation

- ▶ Proper planning of instrumented segment of test piles with due consideration of soil stratification, pile resistance profile (constant or varying profile with depth)
- ▶ Tensile cracking of concrete under tensile test load leading to irreversible stiffness alteration shall be carefully assessed for proper load transfer
- ▶ Solutions :
 - ▶ Identify expected profile of pile-soil friction based on stratification, soil consistency,
 - ▶ Gauge length shall be reasonably small where practical for proper axial load interpretation, instrumented segment assigned for pile load and movement
 - ▶ Minimum one axial load measurement per material stratum preferably at the either sides of the stratum interface
 - ▶ For material strata with varying pile-soil friction with depth, more instrumented segments are needed for refined interpretation of axial load & movement (for best fitting the pile movement profile)
 - ▶ At least one axial load measurement near to pile base for load transfer of mobilised base resistance



References

■ Sources :

- Dunnicliff, J. (1988), "Geotechnical Instrumentation for Monitoring Field Performance". Wiley-Interscience Publication.
- Geotechnical Instrumentation News (<http://www.bitech.ca/news.htm>)
- Liew, S.S. (2010), "Lessons Learned from Case Histories", JKR Sabah One-Day Short Course on Slope Engineering, Promenade Hotel, Kota Kinabalu, Sabah, 30 June 2010
- Liew, S.S. (2010), "Dam Safety Monitoring and Surveillance in Malaysia", Conference on ASIAWATER 2010, jointly organized by The Malaysian Water Association (MWA), 6th – 8th April 2010
- Liew, S.S.; Lim, Wei & Lau, L.S. (2010), "Investigation of Soil Nailed Slope Distress at Fill Ground & Remedial Solutions", The 17th Southeast Asian Geotechnical Conference, Taipei, Taiwan, 10 to 13 May 2010
- Liew, S.S.; Lee, S.T. & Koo, K.S. (2010), "Failure Investigation of Piled Reinforcement Soil Wall & Excessive Movements of Piled Embankment at Soft Ground, Malaysia", The 17th Southeast Asian Geotechnical Conference, Taipei, Taiwan, 10 to 13 May 2010
- Liew, S.S.; Ting, D.I. & Low, Y.H. (2010), "Piling Foundation Design & Construction Problems of Tank Farm in Reclaimed Land over Untreated Soft Marine Clay in Malaysia", The 17th Southeast Asian Geotechnical Conference, Taipei, Taiwan, 10 to 13 May 2010
- Liew, S.S. (2009), "Role of Geotechnical Engineer in Civil Engineering Works in Malaysia", CIE-IEM Joint Seminar on Geotechnical Engineering, Yilan, Taiwan, 26 to 27 August 2009
- Liew, S.S. & Khoo C.M. (2008), "Lessons Learned from Two Investigation Cases of Ground Distresses Due to Deep Excavation in Filled Ground", 6th Int'l Conf. on Case Histories in Geotechnical Engineering, 11-16 Aug 2008, Arlington, Virginia, United States.
- Liew, SS (2008), "Case Studies of Support of Open Excavations and Distressed Retaining Walls in Malaysia" Seminar on "Deep Excavation and Retaining Walls", Jointly organised by IEM-HKIE at Tropicana Golf & Country Resort, Petaling Jaya, Malaysia, 24 March 2008.
- Liew S.S. & Khoo C.M. (2007), "Performance of Soil Nail Stabilisation Works for a 14.5m Deep Excavation at Uncontrolled Fill Ground", Proc. 16th Southeast Asian Geotechnical Conferences, Malaysia.
- Liew S. S. & Tan S. K. (2007), "Performance of Reinforced Soil Wall Supported on Stone Columns", Proc. 16th Southeast Asian Geotechnical Conferences, Malaysia.
- Liew S.S. & Khoo C. M. (2006), "Design and Construction of Soil Nail Strengthening Work over Uncontrolled Fill for a 14.5m Deep Excavation", 10th International Conference on Piling and Deep Foundations, 31 May - 2 Jun 2006, Amsterdam, The Netherlands
- Liew S.S. & Liong C.H. (2006), "Two Case Studies on Soil Nailed Slope Failures", Internationals Conference on slope, 7 - 8 August 2006, Kuala Lumpur



References

■ Sources :

- o Liew, S. S., Liong, C. H. & Low, C. L., (2004), "[Four Landslide Investigations in Malaysia](#)", 15th SEAGC, Bangkok, 22 - 26 November 2004.
- o Liew, S. S. & Choo, E. L., (2004), "[Bending Moment Interpretation of Structural Element with Measured Deflection Profile](#)", Malaysian Geotechnical Conference, 16-18 March, 2004, Sheraton Subang, Petaling Jaya, Malaysia.
- o Liew, S. S., Kowng, Y. W. & Gan, S. J., (2004), "[Interpretations of Instrumented Bored Piles in Kenny Hill Formation](#)", Malaysian Geotechnical Conference, 16-18 March, 2004, Sheraton Subang, Petaling Jaya, Malaysia.
- o Liew, S. S., Gue, S. S. & Liong, C. H., (2003), "[Geotechnical Investigation and Monitoring Results of a Landslide Failure at Southern Peninsula Malaysia \(Part 1: Investigating Causes of Failure\)](#)", International Conference on Slope Engineering, Hong Kong, 8-10 Dec 2003.
- o Liew, S. S., Gue, S. S. & Liong, C. H., (2003), "[Geotechnical Investigation and Monitoring Results of a Landslide Failure at Southern Peninsula Malaysia \(Part 2: Back Analyses of Shear Strength and Remedial Works\)](#)", International Conference on Slope Engineering, Hong Kong, 8-10 Dec 2003.
- o Liew, S. S., Tan, Y. C., Ng, H. B. & Lee, P. T., (2003), "[New Approach of using Jacked Anchors as Reinforcements in Soil Stabilisation Works for a Cut-And-Cover Tunnel with 17m Deep Excavation](#)", International Conference on Foundation, Dundee, Scotland, 2-5 Sep 2003.
- o Liew, S. S., Gue, S. S. & Tan, Y. C. (2002), "[Design and Instrumentation Results of A Reinforcement Concrete Piled Raft Supporting 2500 Ton Oil Storage Tank on Very Soft Alluvium Deposits](#)", Ninth International Conference on Piling and Deep Foundations, Nice, 3 - 5 June, 2002
- o Liew, S. S. (2002), "[Pile Design with Negative Skin Friction](#)" Course Lecture for Geotechnical Engineering at Puteri Pan Pacific Hotel, Johor Bahru
- o Liew, S. S. & Gue, S. S. (2001), "[Massive Creep Movements of Post-Glacial Deposits in Kundasang Areas](#)", GSM-IEM Forum : Engineering Geology & Geotechnics of Slopes, Kuala Lumpur
- o Liew, S.S.; Gue, S. S., & Tan, Y. C. (1999), "[Instrumentation Results on Negative Downdrag Force of Abutment Piles Underneath the Reinforced Earth Wall Embankment](#)", 5th Int.. Symp. on Field Measurements in Geomechanics, Singapore.
- o Machan, G. & Bennet, V. G. (2008), "Use of Inclinometers for Geotechnical Instrumentation on Transportation Projects – State of the Practice", Transportation Research Board
- o Mikkelsen, P. K. (2003), "Advances in Inclinomater Data Analysis", Symposium on Field Measurements in Geotechnics (FMGM) 2003, Oslo, Norway



Thank you

Lord Kelvin (1827 - 1907) :

When you can measure what you are speaking about, and express it in numbers, you know something about it; but when you cannot measure it, when you cannot express it in numbers, your knowledge is of a meagre and unsatisfactory kind; it may be the beginning of knowledge, but you have scarcely in your thoughts advanced to the state of Science, whatever the matter may be.





Session 3 : Case Studies on Ground Improvement Failures

Ir. Liew Shaw Shong

Ground Improvements

- ▶ Case Study 1 : Basal Reinforcement (Distress)
- ▶ Case Study 2 : Impact of Embankment on PVD Treated Ground (Failure)
- ▶ Case Study 3 : Performance of Stone Columns Treated Ground (Not a failure case, but interesting performance)



Role of Extendible Basal Reinforcement for Embankment Construction Over Soft Soils

- ▶ Introduction
 - ▶ Problem Statements & Distress
 - ▶ Back Analysis
 - ▶ Discussions
 - ▶ Conclusions
 - ▶ Recommendations
-



Introduction

- Embankment → Raised fill platform with side slopes to support structure and infrastructure developments.
 - Stage construction + additional reinforcement → Ensure acceptable side slope stability
 - Basal reinforcement → To minimise spreading failure of compacted embankment fill over weak supporting subsoils
-



Basal Reinforcement

- Shall be designed in accordance with BS8006.
- Consideration → Strain compatibility between embankment fill and basal reinforcement system.
- Tensile strain in basal reinforcement shall be controlled to avoid cracking in embankment fill.

Basal Reinforcement

- If the embankment is strained to excessive tensile crack, the embankment fill material strength is doubtful.
- Thus, case study of an instrumented embankment construction with extendible basal reinforcement have been used.
- This may call for a review of the permissible strain of extendible basal reinforcement with brittle compacted fill.

Problem Statement & Distresses

▶ Problem Statements


- ▶ Embankment Fill over Soft Deposits
- ▶ PVD with Staged Construction
- ▶ Basal Reinforcement for Temporary Embankment Stability
- ▶ BS8006
- ▶ Strain Incompatibility

▶ Distresses

- ▶ Longitudinal flexural cracks on embankment surface



Embankment Distresses



Embankment Distresses



Embankment Distresses

Alligator cracks
observed on site.



Embankment Distresses



Embankment Distresses



Embankment Distresses




Excavation on cracks found
after 1m surcharge removal




Instrumentation Layout

Instrumentation Layout
Plan at Distresses area




Instrumentation Results

Fill Thickness and Settlement of Embankment with time monitoring by SG580




Instrumentation Results

Inclinometer I6 Monitoring Results



Finite Element Model



Finite Element Model

Back analysis to match lateral deformation and settlement profiles.


Two cases were modelled for back analysis:-

Case 1: Ultimate strength (600kN/m) mobilized at 10%

Case 2: Ultimate strength (140kN/m) mobilized at 1%


Finite Element Model

Comparison of Back Analysed Settlement Trend With Actual Measurement (Case 1)



Finite Element Model

Comparison of Lateral Displacement Profile (Case 1)




Summary of Back Analyses

| Stage | Tensile Stiffness | Mobilised Tensile Load / Tensile Strain | Maximum Lateral Deflection at Edge of Embankment (mm) |
|-------|-------------------|---|---|
| S1 | Case 1 | 40.6kN/m / 0.68% | 267 |
| | Case 2 | 65.9kN/m / 0.47% | (173) |
| R1 | Case 1 | 41.8kN/m / 0.70% | 295 |
| | Case 2 | 67.4kN/m / 0.48% | (180) |
| S2 | Case 1 | 64.6kN/m / 1.08% | 400 |
| | Case 2 | 106.8kN/m / 0.76% | (253) |
| R2 | Case 1 | 67.4kN/m / 1.12% | 425 |
| | Case 2 | 110.3kN/m / 0.79% | (265) |



Probable Mechanism



Discussion

- ▶ Strain incompatibility between basal reinforcement and embankment fill could potentially cause embankment cracking.
- ▶ Average tensile strain of underlying weak subsoils is more than max. tensile strain in basal reinforcement.
- ▶ Results of back-analysis → indicated mobilised tensile strength and strain < conventional assumed values for LEA stability analysis.



Conclusion

- ▶ Longitudinal cracks → Outcome of plastic straining of upper weak alluvium within the underlying subsoil below the embankment loading.
- ▶ Review on current design practice by arbitrarily adopting unrealistic high mobilised strength is needed.
- ▶ Wishful high tensile strain assumed in LEA can lead to misrepresentation on safety margin of embankment.



Recommendations

- ▶ Counterweight berm was proposed to solve the strain incompatibility between basal reinforcement and the subsoil.
- ▶ Instrument on basal reinforcement to reveal the distribution profile and performance of installed basal reinforcement.




Case 2: Case study on Piled Supported Embankment Failure



Site Conditions

- ▶ Embankment (maximum 5.4m high) with Piles & Ground Improvements
 - ▶ Ch3328 to Ch3375 (Top 10m soft Clay, $S_u = 10\sim15\text{kPa}$)
- ▶ Distressed Abutment
 - ▶ Abutment A @ Ch3266 (Top 15m soft Clay, $S_u = 13\sim18\text{kPa}$)
 - ▶ Abutment B @ Ch3328 (Top 9m soft Clay, $S_u = 7\sim12\text{kPa}$)



Findings from Site Inspection

- ▶ Piles & slab of piled embankment suffered structural distress
- ▶ Settlement of 0.4 to 1.0m beneath piled embankment due to consolidation of subsoils under the working filled platform.
- ▶ Bearing distortions confirmed : Bridge deck moving from Abutment B towards Abutment A

Site Inspection Findings

- ▶ Piled Embankment 30m from Abutment B shown structural distress



29

Site Inspections Findings

- ▶ Piles of Piled Embankment has shown flexural cracks



30

Site Inspections Findings

- ▶ Damaged piled embankment slab damaged & 100mm gap at slab joint



31

Site Inspections Findings

- ▶ Settlement of 0.4 to 1.0m under the Piled Embankment



32

Site Inspections Findings

► Bearing distortion at Pier P2





33

Site Inspections Findings

► Bearing distortion at Pier P1



34



Investigation Findings

▶ Embankment (5.4m high)

- ▶ Ch3375 : $FOS \cong 1.0$ at Embankment on Ground Treatments
- ▶ Causation : Inadequate FOS => Embankment instability exerting lateral stress to Piled Embankment on free standing piles due to subsoil consolidation

▶ Distressed Abutment

- ▶ Abutment B : Laterally pushed by **unstable embankment** behind piled embankment
- ▶ Abutment A & Two piers : Affected by lateral thrust from Abutment B (**No observable distresses** at the abutment pile foundation after exposure of piles)




37

Abutment Remedial Design

▶ Abutment Distress (Ch3266 to Ch3328)

- ▶ Remedial proposal :



38

Conclusions

- ▶ Weak post-treatment soil strength unable to support embankment
- ▶ Creep movement of weak subsoil beneath embankment coupled with embankment instability due to low FOS
- ▶ Further consolidation of weak overburden soil, the lateral resistance of piled embankment in free standing pile conditions is weaken
- ▶ Monitored bridge displacement confirmed pattern of lateral movement of entire bridge & piled embankment
- ▶ Structural damage on embankment piles was expected as structural threshold has reached
- ▶ Use of residual strength is needed for rectifying failed embankment



39

Recommendations

- ▶ Construct new embankment slab at least 1m below the failed slab to prevent further consolidation settlement
- ▶ Extend piled embankment for embankment fill higher than 2m & provide isolation gap at the slab/abutment interfaces
- ▶ Use of higher strength RC pile for embankment piles
- ▶ Use of geotextile reinforcement to isolate embankment fill from both abutments to reduce direct lateral earth pressure on abutments



40


Case Study 3 : Performance of Stone Columns Supported RS Wall



- Original Topography
 - Subsurface Information
 - Adopted Foundation System for RS Wall
 - Design Consideration
 - QA/QC During Construction
 - Design Verification
 - Conclusion
-

Original Topography of Site

- Original ground is hilly
- Surface runoff towards natural valley area
- Within proximity of previous water stream


→ Weak deposits






SUBSURFACE INFORMATION


- Residual Soil
- Granitic Formation
- Intermediate Boulders



S.I. Layout Along RS Wall




Subsurface Profile Along RS Wall



Soft Compressible Layer

Implications



ADOPTED FOUNDATION DESIGN SYSTEM FOR RS WALL

- 10m high reinforced soil wall on up to 12m thick soft compressible subsoil

➔ Stone column

- 1m diameter
 - 2m centre to centre spacing
-

ADOPTED FOUNDATION DESIGN SYSTEM FOR RS WALL

■ Reasons

- Reinforcement of weak subsoil
 - Drainage for dissipation of excess pore pressure generation
 - Improving strength and deformation properties of soil
-

DESIGN CONSIDERATIONS

- **Bulging** of individual stone column
- **General shear** of stone column
- **Stress distribution** between stone columns and subsoil

DESIGN CONSIDERATIONS

- **Bearing capacity** of subsoil and stone column
- **Global stability** of RS wall
- Overall **ground settlement after improvement**

QA / QC DURING CONSTRUCTION

- Material control
- Appropriate **termination criteria** of stone column installation
- Verification test (plate load test)


Material Control

- Clean, hard, durable
- Chemically inert natural materials

| Test | Standard | Criteria | Frequency |
|----------------------|-------------|------------------------------------|---------------------------------------|
| Crushing Value | BS 882:1992 | <30% | 1 test per 30,000 tonnes of aggregate |
| Los Angeles Abrasion | ASTM C131 | Max loss of 40% at 500 revolutions | |
| Flakiness Index | BS 882:1992 | <30% | |
| Sulphate Soundness | ASTM C88 | <12% | |

Material Control

(Allowable grading of stone aggregates)



Range of Soils suitable for Vibro Compaction Methods


(Baumann and Bauer, 1974)

Termination Criteria

- Hydraulic pressure in the vibratory probe = 190 bars

**TO BE VERIFIED BY PLATE LOAD TEST DURING
FIRST COLUMN INSTALLATION**

Termination Criteria




Verification Test (Plate Load Test)



Verification Test (Plate Load Test)




Verification Test




DESIGN VERIFICATION

- Finite element method (FEM) analyses using PLAXIS
- Monitoring instrumentation scheme


PLAXIS Model & Analyses




Instrumentation Monitoring Scheme




Instrumentation Monitoring Scheme



Instrumentation Monitoring Scheme




Inclinometer with Magnetic Extensometers




Details of Displacement Markers


Instrumentation Results



Instrumentation Results




Instrumentation Monitoring Scheme




Instrumentation Results


Inclinometer at CH84.6m (A-A) @SDM18




Instrumentation Results




Instrumentation Results



Instrumentation Results



Instrumentation Results



Legend

- Current
- Predicted

(δ/p_1) Diagram with Factor of Safety (After Matsuo et al, 1977)

CONCLUSIONS

- Successful installation of stone columns within economical means
- To consider
 - ➔ Design Aspects
 - ➔ Quality Assurance and Quality Control during construction

CONCLUSIONS

- Use Observational Method and Finite Element Analysis
- Matsuo plot can also be applied to verify the FOS of RS wall



Thank You



Session 4 : Case Study of Slope Failures/Landslides in Tropical Residual Soils

Presented by:
Ir. Liew Shaw Shong




Contents

- A. Creep Movement of Slopes, Sabah.
- B. Cut Slope Failure in Skudai, Johor.
- C. Cut Slope Failure at Gua Musang, Kelantan.
- D. Cut Slope Failure at Kuala Lumpur.
- E. Filled Slope Failure at Salak Tinggi.
- F. Soil Nailed Slope Failure at Pahang.
- G. Cut Slope Failure at Kedah.

Case Studies




A. Creep Movement of Slope, Sabah





Site Background


- RL1335m to RL1500m.
- Terrain : Undulating/Sloping.
- Outcrops: Granitic boulder/ Grey Shale/ Sandstones.
- Deposits of Pinosuk Gravel from Mt. Kinabalu.
- Glaciation & Ancient Mudflow.



SI & Laboratory Testing

- Six Boreholes & Inclinometers
- Six Piezometers (GWT : 1.5~2.5m)
- C.I.U. Tests & Direct Shear Box Tests ($\phi' = 21^\circ$, $c' = 10\text{kPa}$).
- Others Properties : $w_n = 7\%$ to 13% ,
 $\gamma_{\text{bulk}} = 21 \sim 23.7\text{kN/m}^3$
- Normally Consolidated

Shear Strength Test Results



Monitoring Results

- Inclinometers detected slip surface.
- Lateral Movement:
- Direction : $225^\circ \sim 250^\circ$
- Max. Movement : 140mm (IN-4)
- Rate of Movement : 2~14mm/week (Max. 21mm/week)

Inclinometer Movement Rate




Engineering Assessment

- Interpreted laboratory shear strength parameters are too high to cause instability.
- Back-analysis shear strength parameters:
 $\phi' = 13^\circ \sim 16^\circ$, $c' = 0 \sim 5 \text{ kPa}$

Findings

- Slip Surface : 6m (higher ground) to 15m (lower ground).
- Movement Direction: almost parallel to road alignment, towards river.
- Back-analysed shear strength < Interpreted laboratory test results.



Recommendations

- Carry out continuous sampling at shear plane to collect samples for testing.
- Carry out ring shear test or multiple reversal direct shear box test to determine residual strength.

B. Cut Slope Failure in Johor



Site Background


- RL54m to RL106m.
- Terrain : Sloping.
- Geology: Mainly basic intrusive gabbro and intermediate intrusive.
- Two berms cut slope 1V:1.5H.
- Slope collapsed after heavy downpour.



SI and Instrumentations

- SI and instrumentation for failure investigations:
- 4 boreholes within failed mass area.
- 3 inclinometers.
- 3 observation wells and 1 standpipe piezometer.


SI Layout Plan



Instrumentation Results

- IN-1 and IN-2 were sheared off at 10.5m and 12.0m below ground.
- IN-3 sheared off at 2.5m below ground.
- Observation wells were also sheared off.

Interpreted Slip Surfaces




Laboratory Test Results

- CIU test :
 - a. Peak strength – $c' = 3.5 \text{ kPa}$, $\phi' = 32^\circ$
 - b. Critical state strength – $c' = 0 \text{ kPa}$, $\phi' = 29^\circ$
- Direct Shear Box test : (fairly scattered)
 - a. Peak strength – $c' = 15.7 \text{ kPa}$, $\phi' = 24^\circ$
 - b. Residual strength – $c' = 5.9 \text{ kPa}$, $\phi' = 20^\circ$

Back-Analysis

- Back-analyses were performed for 2 conditions:
 - a. Slope profile after cutting, before failure. (critical state strength)
 - b. Slope profile after failure. (residual strength)
- The interpreted slip surface and monitored groundwater level is used for back-analysis.

Slope Profile for Back Analysis





Back-Analysis Results

- Back-analyses using PC-Stabl6 and Plaxis.
- Back-analyses results :
 - a. Mobilised shear strength : $c'=0$ kPa, $\phi'=24^\circ - 25.9^\circ$
 - b. Residual strength : $c'=0 - 0.5$ kPa, $\phi'=14.4^\circ - 15^\circ$

Residual Strength

- Comparisons with literature:
 - a. Residual friction angle – Liquid Limit.
 - b. Residual friction angle – Clay size fraction.
- Back analysed residual friction angle are lower as compared to literatures.





Findings and Recommendations

- The investigation deduced that there is a thin layer at the slip surface with low shear strength.
- Boreholes are not able to capture the thin layer and could only be detected by inclinometer.
- Residual shear strength should be used for remedial design works.

C. Cut Slope Failure at Gua Musang, Kelantan



Site Observations



Site Background

- RL210m to RL330m.
- 7 Upper berms of 1V:1H Cut Slope & 5 Lower berms of 4V:1H Soil Nailed Slope
- Soil Nail = 12m with spacing of 1m(V):1m (H)
- Geology: Shale Facies in Gua Musang Formation which mainly consists of Mudstone & Sandstone
- A massive slope failure occurred before soil nails were installed at the lowest berm.

Geological Mapping

- 'Line Mapping' Method
 - To measure & record discontinuity along the exposed slope face
 - To detect anomalous features
 - Schmidt Rebound Hammer to give indication on weathering condition


Site Observations




SI & Laboratory Works

- 2 boreholes
- 3 C.I.U. Tests
- 2 Multiple Reversal Direct Shear Box Tests
- Grade IV Material
 - a. Peak strength – $c'=30\text{kPa}$, $\phi'=33^\circ$
 - b. Residual strength – $c'=0\text{kPa}$, $\phi'=33^\circ$
- Grade III Material
 - a. Peak strength – $c'=30\text{kPa}$, $\phi'=39^\circ$
 - b. Residual strength – $c'=0\text{kPa}$, $\phi'=33^\circ$

SI Layout Plan




Slope Profile




Engineering Assessment

Slope Stability Analyses




Limit Equilibrium Method

Slope Stability Analyses



Limit Equilibrium Method


Finite Element Analyses




Dev. of Plastic Points In FEM
(After Cutting of 2 Upper Berms)

Plastic Points
■ Mohr-Coulomb point ■ Tension cut-off point


Finite Element Analyses



Finite Element Analyses




Finite Element Analyses



Dev. of Plastic Points In FEM
(After Cutting of 9 Upper Berms)

Plastic Points
■ Mohr-Coulomb point ■ Tension cut-off point


Finite Element Analyses



Dev. of Plastic Points In FEM
(After Cutting of 11 Upper Berms)

Plastic Points
■ Mohr-Coulomb point ■ Tension cut-off point

Finite Element Analyses



Findings

Possible Causes of Failure

- Steep upper cut slope of 1V:1H.
- Inadequate soil nail length of 12m.
- Day-lighting geological structures of Grade III to V materials at the upper cut slope.
- Progressive failure have leaded to develop of a continuous shear surface.


D. Cut Slope Failure at Kuala Lumpur



Site Observations



Closed Drain at
Toe of Slope



Damaged
Berm Drain


Site Background

- The cut slope with 6 berms was formed in 90s
- Slope gradient varies from 1V:1.72H (lowest berm) to 1V:1H (highest berm)
- RL75m to RL110m.
- Geology: Granite formation.
- Slope movement was detected in Nov 2002 and obvious tension cracks were found at the lowest three berms.


SI & Instrumentation

- SI and instrumentation for failure investigations:
 - 3 boreholes
 - 22 Mackintosh Probes
 - 2 inclinometers
 - 3 observation wells

SI & Instrumentation Layout Plan



Slope Profile



Laboratory Test Results


- 8 C.I.U. tests
- 2 Multiple Reversal Direct Shear Box Tests
- Interpreted Moderate conservative soil parameters:

$$c'=2\text{kPa}, \phi'=31^\circ$$

Instrumentation Results

- Max lateral movement (IN. 1)
~ 8mm with the depth of shear plane of about 7m tallies with stability analyses.

Slope Stability Analyses




Limit Equilibrium Method

Proposed Remedial Works

- Installation of Soil Nails (12m, 18m and 27m).
- Installation of horizontal drains.
- Repairing and re-construction of berm drains.

Proposed Remedial Works



Completed Soil Nailed Slope



Findings

Possible Causes of Failure

- The gradient of the cut slope is steep and is not stable in long term
- Slope strengthening works with installation of soil nails and subsoil drainage system have proven an effective solution to stabilise the distressed slope.

E. Fill Slope Failure at Salak Tinggi



Site Background

- Fill slope over a natural valley to form platform.
- Three berms slope : 20m height.
- Another three slopes on top of platform.
- Geology: Kenny Hill formation with interbedded sandstone and siltstone.
- Slope collapsed after heavy downpour.



Site Observations

Clogged Drain

Surface Runoff
overflow the
platform

platform and traveled
valley.

- Failed mass traveled
downhill along valley

Site Observations

Failed Mass
Traveled Downhill

g

SI and Laboratory Tests

- 3 boreholes were sunk.
- Sandy material – weathering from sandstone.
- CIU tests.
- Interpreted shear strength: $c'=2\text{kPa}$, $\phi'=32^\circ$.

Probable Causes of Failure

- Valley terrain.
- Steep fill slope gradient – steepest gradient of 1V:1H.
- Marginal FOS when groundwater level rises near to ground surface.
- Poor drainage system lead to saturation and erosion.

Remedial Works

- Fill embankment over valley.
- Fill embankment comprises of :
rock toe and seven berm slope (1V:2H).
- Provision of extensive subsoil drainage:
French drain and drainage blanket.
- Upgrading and construction of new
drainage system.



After Completion of
Construction Works



F. Soil Nailed Slope Failure at Pahang

7.5 berms soil nailed slope




Site Observations



Site Background

- Geology: Granite and metamorphic rocks
- Slope with varying degrees of weathering: rock to soil.
- 7.5 berms of 4V:1H Soil Nailed Slope
- Maximum height = 45m
- 12m soil nail length at 1.5m c/c


Site Plan showing Failure Area




SI & Laboratory Works

- 2 boreholes at the slope.
- 3 Consolidated Isotropically Undrained Triaxial (C.I.U.) tests.
- 6 Direct Shear Box Tests.
- Hoek-Brown failure criteria for weathered rock mass.


Interpreted Subsoil Profile




Shotcrete Facing as per Construction Drawing



Shotcrete Facing as Constructed at Site




Facing Failure Mode for Soil Nailed Wall



Note: Figure extracted from
"The Manual for Design
and Construction of
Soil Nail Walls" FHWA

Slope Stability Analysis



Findings

Possible causes of failure:

- Inadequate design of shotcrete facing of soil nailed slope.
- FOS against overall failure is inadequate and marginally stable.
- Rainfall/groundwater is not a triggering cause to failure.

Recommendation & Conclusion

- SI and geological mapping for slope are essential for slope design especially for soil nailed slopes.
- Design shall be reviewed during construction to verify the design assumptions especially subsoil profile.
- Progressive failure mechanism is prominent in high cut slope.

Recommendation & Conclusion

- 4 modes of failure: nail tendon failure, nail pull-out failure, facing failure and overall failures shall be checked. Facing failure check is usually neglected.
- Facing design is critical especially when soil nailed slope is steep and high.
- More research is required on establishing engineering parameters of weathered rock mass of different formation in Malaysia.


G. Cut Slope Failure at Kedah



Site Background

- High ground RL300m – RL350m.
- Bedrock : Intact granite bedrock with prismatic feldspar phenocrysts.
- 5 to 6 berms : 27m height.
- Slope gradient 1V:1H.
- Two failure incidents:
 - a. Localised stretch (50m).
 - b. Major slope failure (250m) after 1 month following heavy rainfall.





Laboratory Test Results

- Sandy material within failed mass.
- CIU test :
 - a. $c_p' = 2\text{kPa}$, $\phi_p' = 30^\circ$
 - b. $c'_{\varepsilon(\max)} = 1.9\text{kPa}$, $\phi'_{\varepsilon(\max)} = 28^\circ$
- Back Analysis :
 - a. $c_m' = 0\text{kPa}$, $\phi_m' = 30^\circ$

Findings

Possible causes of failure:

- FOS against overall failure indicates the slope is at the verge of failure for the water level measured during investigation.
- Rainfall leading to rise of groundwater is the triggering cause to failure.

Conclusions

- Main Contributory Factors for Slope Failure (Static) :
 - Inherent weak strength & sensitive materials
 - Adverse geological & hydro-geological features
 - Morphological features
 - Steep slope geometry
 - Gravity force
 - Weathering
 - Inadequate design & lack of maintenance
- Triggering Factors (Dynamic) :
 - Rainfall/leaking utilities/rapid drawdown (soil saturation/ rise of GWT)
 - Human disturbance (excavation/surcharge/vegetation removal/vibration)
 - Earthquake/volcanic eruption/thunder
 - Erosion

Thank You





G&P Geotechnics Sdn Bhd

SESSION 5 : Case Studies of Foundation Distresses



By Ir. Liew Shaw Shong




Case Study 1 : Reduced Empty Pre-bored Jack-in Pile Capacity in Meta-Sedimentary Formation

- Overview of pile installation & Performance
- Subsurface Information
- Contractually Scheduled MLT Results
- Additional MLT Results
- Investigation Findings
- Conclusions & Recommendations

Overview Foundation System

- 400mm RC square pile
- Pre-boring was deployed to
 - Overcome intermittent hard layer
 - Avoid shallow pile penetration
- Jack-in pile installed inside pre-bored hole

Pre-bored Hole Diameter

| 600mm diameter | 500mm diameter | 550mm diameter |
|---|---|--|
|  Pre-bored hole |  400mm dia. RC Pile |  |
| Too large pre-bored hole | Too small pre-bored hole | Compromised pre-bored hole (Adopted) |


Void in Pre-bored Hole Annulus



Collapsed Debris in Pre-bored Hole Annulus



Actual Scenario of Installed Piles



MLT Results

| Maintained Load Test (MLT) | Pre-bored Diameter (mm) | Pile Penetration below Piling Platform (m) | Max. Jack-in Load at Termination (kN) | Achieved Maximum Test Load (kN) | Pile Top Settlement | |
|----------------------------|-------------------------|--|---------------------------------------|---------------------------------|----------------------|------------------------|
| | | | | | At Working Load (mm) | At Max. Test Load (mm) |
| MLT 1 | 600 | 9.40 | 2160 | 2220 (1.71xWL) | 14.0 | 46.00 |
| MLT 2 | 500 | 9.30 | 2600 | 2220 (1.71xWL) | 23.50 | 42.00 |
| MLT 3 | 550 | 12.50 | 2860 | 2600 (2.00xWL) | 5.80 | 21.80 |
| MLT 4 | 550 | 9.50 | 2860 | 1406 (1.50xWL) | 16.50 | 24.50 |
| MLT 5 | 550 | 13.50 | 2860 | 1950 (1.50xWL) | 8.50 | 13.00 |


Jack-in Pile Termination Criteria

- All piles were jacked to 2.2 times pile working load
- Settlement < 5mm during 30 seconds holding period for 2 consecutive times

BUT

- Max Test Load \leq Jack-in Load
- Non-conforming Piles Settlement Criteria



Boreholes Information







Photos of Exposed Subsoils



Contractually Scheduled MLT Results











Additional MLT Results

Additional MLT

- 3 nos additional MLT at various penetration below pre-bored base:
- MLT6 – 0.5m below pre-bored base
- MLT7 – 1.5m below pre-bored base
- MLT8 – 2.0m below pre-bored base


Additional MLT






| MLT | Pre-bored Diameter (mm) | Pile Penetration below Piling Platform (m) | Max. Jack-in Load at Termination (kN) | Achieved Maximum Test Load (kN) | Pile Top Settlement | |
|-------|-------------------------|--|---------------------------------------|---------------------------------|----------------------|------------------------|
| | | | | | At Working Load (mm) | At Max. Test Load (mm) |
| MLT 1 | 600 | 9.40 | 2160 | 2220 (1.71xWL) | 14.0 | 46.00 |
| MLT 2 | 500 | 9.30 | 2600 | 2220 (1.71xWL) | 23.50 | 42.00 |
| MLT 3 | 550 | 12.50 | 2860 | 2600 (2.00xWL) | 5.80 | 21.80 |
| MLT 4 | 550 | 9.50 | 2860 | 1406 (1.50xWL) | 16.50 | 24.50 |
| MLT 5 | 550 | 13.50 | 2860 | 1950 (1.50xWL) | 8.50 | 13.00 |
| MLT 6 | 550 | 9.50 | 2860 | 1950 (1.50xWL) | 15.08 | 42.38 |
| MLT 7 | 550 | 10.50 | 2860 | 2400 (1.85xWL) | 11.29 | 41.93 |
| MLT 8 | 550 | 11.00 | 2860 | 2600 (2.00xWL) | 10.30 | 50.35 |


Investigation Findings



Analogy of Footing



Bearing Improvement with Toe Confinement



Conclusions & Recommendations

- Pile performance improved with longer pile penetration below pre-bored base
- Existence of pile toe softening due to relaxation of pile tip founding material
- Sufficient pile penetration below pre-bored base is important
- Recommend to seal the pre-bored hole with grout

Case Study 2: Pile Heave & Lateral Soil Displacement

- ▶ Rapid pile installation in **incompressible** soft soil induces
 - ▶ Vertical heave in shallow depth (relatively less confinement from weight of overburden soils)
 - ▶ Lateral displacement in deeper depth (with soil confinement)
- ▶ Consequences :
 - ▶ **Up-heaving soil movement** causes **tensile stress** on pile & toe lift up during driving & downdrag after pore pressure dissipation
 - ▶ **Lateral soil displacement** causes **flexural stress** on pile & pile deviation
 - ▶ Excessive combined tensile and flexural stresses lead to **pile joint dislodgement**
 - ▶ Excessive foundation settlement in post construction (**pile toe uplifting & downdrag settlement**)




Pile Joint Dislodgement

- ▶ Pile joints could be dislodged due to excessive flexural and tensile stresses induced by ground heave and radial soil displacement
- ▶ Detectable using High Strain Dynamic Pile Test (HSDPT)



Mechanism of Pile Heave & Soil Displacement



Case Study - HSDPT


- ▶ Monitoring of pile top settlement during the HSDPT re-strike tests is summarised as below:

| Cumulative Pile Top Settlement (mm) | Pile C | Pile A | Pile B | Pile D | Pile E |
|---------------------------------------|--------|--------|--------|--------|--------|
| Upon resting 7-ton hammer on pile top | 80 | 98 | 125 | 103 | 92 |
| At the end of Restriking Test | 275 | 399 | 497 | 186 | 182 |



Case Study - HSDPT


- ▶ Pile B
- ▶ Initial Blow



Case Study - HSDPT

- ▶ Pile B
- ▶ Blow No. 4


First Joint Discontinuity closed up after few blows; Two Pile Lengths was revealed with another Major Discontinuity at new 'toe' (reflection)



Case Study - HSDPT

- ▶ Pile B
- ▶ Blow No. 17


Second Major Joint Discontinuity also disappeared; Total of Three Pile Lengths was observed




Case Study - HSDPT

- ▶ Pile B
- ▶ End of Blow



Minor velocity reflections were observable at first and second pile joints



Pile Heave Monitoring Program



Pile Heave Monitoring Result




Summary

- ▶ **Ground heave & radial soil displacement** due to rapid installation of displacement pile in soft incompressible soft clay can pose serious integrity problem on pile foundation.
- ▶ Solutions :
 - ▶ Use **larger** pile spacing & **reduce rate** of clustered pile installation for adequate time for dissipation of excess pore pressure
 - ▶ Simultaneous pile installation at mirror pile location from **centre outwards** to minimise net lateral displacement, but this improves nothing on ground heave
 - ▶ Stronger **pile structural strength & joint** to withstand tensile & flexural stresses
 - ▶ **Staggered pile installation sequence** or install piles at **alternate** locations
 - ▶ **Restrike all piles with HSDPT** to detect pile integrity if ground or soil heave is observed.


Case Study 3 - Geotechnical Review on Foundation Settlement

- The underlying soils are mainly **soft & compressible soils**
- Characteristics:
 - Compressible
 - Settling under loading (eg. fill) with time

General Subsoil Profile



General Subsoil Profile



Site Observations

- Cracks on wall – mostly diagonal – due to differential settlement



Site Observations

- Distress due to differential settlement



Probable Causes

1. Collapse settlement of unsaturated fill

- Occurs when saturation of loose fill (eg. during raining)
- S.I. results confirmed existence of fill at most areas

Probable Causes

2. Long term settlement of compressible soft soil


- Occurs when filling over soft soil
- S.I. results confirmed existence of soft soil

Probable Causes


3. Left-over soft deposits within silt trap & temporary drains

- Results in localised soft spots – more compressible
- Additional S.I. results confirmed existence of soft soil

Phase 2D1



Probable Causes







Remedial Works by Specialist Contractor

- **Grouting** has been carried out by specialist contractor at Block 1 of Phase 2C2
- Purpose: Fill in voids and densify compressive soft soil to eliminate ground settlement




Remedial Works by Specialist Contractor


- Settlement is stabilising after grouting treatment



Monitoring Results

- Crack monitoring (3 months)
- Settlement monitoring (10 months)
 - Ground settlement
 - Column settlement





Thank You



SESSION 6 : Case Studies of Wall Failures

Ir. Liew Shaw Shong



TWO CASE STUDIES OF COLLAPSED TEMPORARY EXCAVATION USING CONTIGUOUS BORED PILE WALL

Ir. Liew Shaw Shong



Outline of Presentation

- Common Probable Causes of Excavation Failure
- Investigation Procedure
- Case Study 1 & Case Study 2
 - ▣ Background
 - ▣ Chronological Events
 - ▣ Causes of Failures
 - ▣ Lessons Learnt

Common Probable Causes of Excavation Failure

- Describe the product or service being marketed
- A) **Natural Disasters** : fire, earthquake, tsunami, tremor, wind, rainfall and flood
- B) **Act of Sabotage**: explosive substances
- C) **Material Defects**: reused steel strutting sections with poor conditions, concrete properties
- D) **Design**: modelling and design parameters, robustness and ductility
- E) **Construction**: sequences of works, excavation depth
- F) **Maintenance**: drainage system, no timely review of instrumentation results

Investigation Procedure


1. Check safety factor of the original design
2. Check the as-built construction for any deviations from original design
3. Identify design shortcomings, material defects, workmanship deficiencies, if any
4. Interview design team, construction management team, site personnel and eye witnesses
5. Consult other experts if required, for matters beyond the investigator's expertise or knowledge of the facts
6. Identify possible collapse scenarios and rationalise conflicting facts or evidences
7. Determine the major contributory and triggering factors that cause the collapse
8. Conduct advanced non-linear analysis /tests to ascertain the collapse mechanism
9. Confirm the collapse mechanism with those from facts and evidences
10. Write report

CASE STUDY 1 (CS1)


CS1: Excessive Movement of CBP Wall

- Two-Storey Basement
- Temporary Excavation with Berms & Raking Struts to Lower Basement Slab
- Distresses observed in the middle of Temp. Excavation
 - ▣ Ground Distress
 - ▣ CBP Wall tilted and Structurally damaged
- Remedial Works
- Summary of Findings & Lessons Learnt


CS1: Excessive Movement of CBP Wall



CS1: Excessive Movement of CBP Wall



CS1: Excessive Movement of CBP Wall



CS1: Excessive Movement of CBP Wall



CS1: Excessive Movement of CBP Wall




Ground Distress at Active Wedge



Repairing of CBP Pile


CS1: Excessive Movement of CBP Wall



CS1: Excessive Movement of CBP Wall


Back Analysis

- Finite Element analysis (PLAXIS) to simulate the construction sequences of excavation & to investigate the probable causes of ground distresses & wall movements.



CS1: Excessive Movement of CBP Wall

Remedial Solution



CS1: Excessive Movement of CBP Wall



Repairing Crushed CBP



Shear Failure of Corbel Support


CS1: Excessive Movement of CBP Wall

□ Summary of Findings & Lessons Learnt


- Building platform formed over **natural valley** containing thick fill over previous **soft deposits** provides prerequisite condition for ground distresses during temporary localized deep pile cap excavation & removing passive berm excessively without planned strut supports.
- Occurrence of tension cracks during initial open excavation and installation of sheet piles suggested that the underlying subsoil at the valley area are inherently vulnerable to ground disturbance and hence are prompted to distressing.
- Perched groundwater regime can occur in backfilling over natural valley leading to unfavourable behaviour of backfill.
- Desk study of pre-development ground contours is highly recommended.

CASE STUDY 2 (CS2)


CS2: CBP Wall Failure



CS2: Retaining Wall System




CS2: Retaining Wall System



CS2: Important Events Before Collapse




Original struts position for Struts D, E and F with passive berm retained at Gridlines G and H.



CS2: Important Events Before Collapse



Water pipe burst incident on Day 227 which caused the steel corbel for strut F being sheared off as reported.



Observations of investigator:


Although strutting subcontractor did not design the strutting system for one strut failure scenario, the retaining wall system still managed to distribute the loads from Strut F vertically to soil and laterally to Struts D & E and passive berm safely but with large incremental movement registered at Inclinator I_{IC4} .

The water pipe burst incident on Day 227 could have weakened the strut corbel connection for Strut F and stressed the CBP walls towards its structural ultimate limit state.

CS2: Important Events Before Collapse



Water pipe burst incident on Day 227 which caused the steel corbel for strut F being sheared off as reported.




Observations of investigator:

Although strutting subcontractor did not design the strutting system for one strut failure scenario, the retaining wall system still managed to distribute the loads from Strut F vertically to soil and laterally to Struts D & E and passive berm safely but with large incremental movement registered at Inclinator I_{IC4} .

The water pipe burst incident on Day 227 could have weakened the strut corbel connection for Strut F and stressed the CBP walls towards its structural ultimate limit state.

CS2: Important Events Before Collapse



Strut F was reinstated. After installation of struts G and H, temporary passive berm along Gridlines G and H were progressively removed.



CS2: Important Events Before Collapse



The removal of temporary passive berm has caused incremental ground movement that led to another water pipe burst incident on Day 248. This water pipe leakage had triggered CBP wall collapse tragedy on Day 248.



CS2: Video Clip on Wall Failure

CS2
248



CS2: Video Clip on Wall Failure

CS2
248



CS2: Flow of Wall Failure on Day 248



- 1) Water pipe burst (behind the CBP Wall)
- 2) Steel corbel connection at Strut F sheared-off
- 3) Failure of strutting system to re-distribute the failure load to adjacent struts
 - Steel corbel connections at Struts D and E sheared off due to sudden increased in strut force
 - Struts G and H buckled due to sudden increase in strut force
- 4) Failure of CBP walls due to loss of lateral supports (struts)
- 5) CBP wall failed rotationally and retained earth at active soil wedge in to the excavation site


CS2: Why Wall Collapse

Triggering Factor of Wall Collapse: Increase of water pressure due to repetitive water pipe burst incidents happened at the back lane

Causes of Wall Collapse ??


CS2: Causes of Wall Collapse

1) Adoption of optimistic cohesion parameter by the consultant




CS2: Causes of Wall Collapse

2) Inconsistency of design intent and site execution between consultant and contractor




CS2: Causes of Wall Collapse

2) Inconsistency of design intent and [site execution](#) between consultant and contractor



CS2: Causes of Wall Collapse

3) [Improper lateral restraint bracing system](#) and non-compliance on hole cutting at steel corbel by strutting sub-contractor and no timely review of the retaining wall and strutting designs.



CS2: Causes of Wall Collapse

3) **Improper lateral restraint bracing system** and **non-compliance on hole cutting at steel corbel** by strutting sub-contractor and no timely review of the retaining wall and strutting designs.




Bolt shear off



Steel Corbel with Post-installed Bolting Connection was Lifted-up After Wall Failure



Post-installed Bolts After Wall Failure



As-built Details of Steel Corbel for Strutting

CS2: Lesson Learnt & Recommendation

- **Timely review** on instrumentation monitoring results is important
- **Selection of soil parameters** shall be done carefully based on sufficient lab testing results and local experiences
- **Site supervision team** to make sure the consistency between the design intent and site execution
- **Pay attention on the connection details** and strutting bracing system

CS2: Which connection detail is better?



VS



**Failure Investigation of Piled Reinforcement
Soil Wall & Excessive Movements of Piled
Embankment at Soft Ground, Malaysia**

by **Liew Shaw-Shong**

Introduction

- ▶ Two Case Studies on Failure of Piled Supported Wall under Extreme Lateral Loading
- ▶ Findings in the Forensic Investigation
- ▶ Conclusions & Recommendation

39

Case 1: Case study on Piled Supported Wall Failure

■ 8m RS Wall + 2m L-Shaped RC Wall

- Foundation : Vertical piles + Raked Piles (3 rows each)
- 400mm thick RC Slab
- 3~3.5m RC Monsoon Drain in front of Wall

■ Failure on 4 Jan 2007 - Intense antecedent rainfall from 10 Dec 06 to 29 Dec 06 & Triggering midnight rainfall (20mm/hr)

- When 120m long RS Wall reached soffit of L-Shaped RC Wall

40


Installation of Piles (mid Oct 06)

Installation of Piles (mid Oct 06)



CH 10 to CH 50m

Slab Casting (mid Oct 06)



CH 100 to CH 150m

Backfilling works (mid Oct 06)



CH 150 to CH 220m


Erection of Wall (mid Oct 06)



CH 150 to CH 250m

43

Rainfall Record



44

Retention pond full of water



45

Site Observations

► Panels



- Wet panels & traces watermark
- Highest level of observed seeping water below 2m high L-shaped RC wall
- ∴ Evidence of high water table behind the wall panel

► Pile Foundation


- Flexural plastic hinge pile damage at 1.75m to 2m below slab soffit level
- ∴ Likely due to excessive lateral load on piles



46



Damaged Foundation Piles





49



Investigation Approach



- ▶ Examine induced Axial & Lateral Forces and Moments on Piles at **Design Condition** & **Failure**
- ▶ Lateral earth pressure theory
- ▶ PIGLET to compute pile group load distribution
- ▶ Check FOS against
 - ▶ Pile axial capacity
 - ▶ Pile lateral capacity
 - ▶ Pile structural adequacy (Moment & Shear)




50










Design Scenario A Results

GWT at Top of Monsoon Drain (RL20.18m)

| Pile no. | Axial loads (kN) | Status <840kN | Lateral loads (kN) | Lateral Resistance (kN) | FOS (>2.0) | Moments (kNm) | Ultimate Moment Resistance (kNm) | Load Factor (>1.5) |
|----------|------------------|------------------|--------------------|-------------------------|---------------|---------------|----------------------------------|-----------------------|
| 1 | 261.40 | OK | 37.27 | 86.00 | 2.3 | 13.30 | 62 | 3.1 |
| 2 | 335.82 | OK | 39.50 | 87.00 | 2.2 | 14.00 | 63 | 3.0 |
| 3 | 469.42 | OK | 16.82 | 93.11 | 5.5 | 5.98 | 66 | 7.4 |
| 4 | 482.78 | OK | 13.89 | 93.11 | 6.7 | 4.94 | 66 | 8.9 |
| 5 | 715.15 | OK | 16.16 | 91.00 | 5.6 | 5.75 | 68 | 7.9 |
| 6 | 558.46 | OK | 42.14 | 91.00 | 2.2 | 15.00 | 68 | 3.0 |
| 7 | 288.96 | OK | 44.10 | 86.00 | 1.9 | 15.70 | 62 | 2.6 |
| 8 | 302.52 | OK | 30.15 | 87.00 | 2.9 | 10.70 | 63 | 3.9 |
| 9 | 459.98 | OK | 17.14 | 93.11 | 5.4 | 6.09 | 66 | 7.2 |
| 10 | 568.37 | OK | 20.81 | 93.11 | 4.5 | 7.40 | 66 | 5.9 |
| 11 | 613.76 | OK | 10.10 | 91.00 | 9.0 | 2.38 | 68 | 19.0 |
| 12 | 608.25 | OK | 44.16 | 91.00 | 2.1 | 15.70 | 68 | 2.9 |

59

Design Scenario B (1/3 GWT)



60


Design Scenario B Results

GWT at 1/3 of Retained Height (RL22.0m)

| Pile no. | Axial loads (kN) | Status <840kN | Lateral loads (kN) | Lateral Resistance (kN) | FOS (>2.0) | Moments (kNm) | Ultimate Moment Resistance (kNm) | Load Factor (>1.5) |
|----------|------------------|------------------|--------------------|-------------------------|---------------|---------------|----------------------------------|-----------------------|
| 1 | 204.98 | OK | 62.76 | 86.00 | 1.4 | 22.36 | 59 | 1.8 |
| 2 | 270.28 | OK | 64.82 | 87.00 | 1.3 | 18.10 | 62 | 1.8 |
| 3 | 544.18 | OK | 35.66 | 94.34 | 2.6 | 12.70 | 69.5 | 3.6 |
| 4 | 553.61 | OK | 29.14 | 94.00 | 3.2 | 10.40 | 69 | 4.4 |
| 5 | 823.98 | OK | 38.75 | 93.11 | 2.7 | 13.80 | 68 | 3.3 |
| 6 | 434.67 | OK | 65.72 | 93.11 | 1.4 | 23.40 | 68 | 1.9 |
| 7 | 228.29 | OK | 47.15 | 86.00 | 1.2 | 26.40 | 60 | 1.5 |
| 8 | 240.03 | OK | 48.36 | 87.00 | 1.8 | 17.20 | 62 | 2.4 |
| 9 | 532.65 | OK | 35.57 | 94.34 | 2.7 | 12.70 | 69.5 | 3.6 |
| 10 | 646.49 | OK | 43.20 | 93.11 | 2.2 | 15.40 | 68 | 2.9 |
| 11 | 728.00 | OK | 21.67 | 94.00 | 4.3 | 7.71 | 69 | 6.0 |
| 12 | 491.76 | OK | 70.24 | 94.00 | 1.3 | 25.00 | 69 | 1.8 |

61

Failure Scenario (GWT at Top Panel)



62


Failure Scenario Results

GWT at Top RS Wall Panel (RL27.0m)

| Pile no. | Axial loads (kN) | Status <840kN | Lateral loads (kN) | Lateral Resistance (kN) | FOS (>2.0) | Moments (kNm) | Ultimate Moment Resistance (kNm) | Load Factor (>1.5) |
|----------|------------------|------------------|--------------------|-------------------------|---------------|---------------|----------------------------------|-----------------------|
| 1 | -8 | OK | 110.09 | 68.53 | 0.6 | 39.20 | 41 | 0.7 |
| 2 | 47.19 | OK | 111.38 | 72.52 | 0.7 | 39.60 | 45 | 0.8 |
| 3 | 604.08 | OK | 93.11 | 94.34 | 1.0 | 25.90 | 68 | 1.8 |
| 4 | 615.47 | OK | 93.93 | 94.00 | 1.0 | 21.00 | 69 | 2.2 |
| 5 | 937.95 | NOT OK | 81.91 | 93.11 | 1.1 | 29.70 | 55 | 1.2 |
| 6 | 115.81 | OK | 108.32 | 72.52 | 0.7 | 38.50 | 45 | 0.8 |
| 7 | -1 | OK | 129.92 | 68.53 | 0.5 | 46.20 | 41 | 0.6 |
| 8 | 32.46 | OK | 81.49 | 72.52 | 0.9 | 29.00 | 45 | 1.0 |
| 9 | 589.30 | OK | 93.11 | 94.34 | 1.0 | 25.60 | 68 | 1.8 |
| 10 | 703.97 | OK | 93.93 | 93.11 | 1.0 | 30.90 | 69 | 1.5 |
| 11 | 866.94 | NOT OK | 79.17 | 94.00 | 1.2 | 18.40 | 52 | 1.9 |
| 12 | 180.22 | OK | 117.71 | 72.52 | 0.6 | 41.90 | 45 | 0.7 |



63

Failure Scenario : Water Level 3.33 m From Top Slab



64


Remedial Works



Additional piles (CH 0 m to Ch 50m)


65

Additional Drainage Control on Re-erected Wall



66

Drainage control on Intact Wall




67

Conclusions

- Main causation :
 - Excessive lateral wall force due to high water table rise from prolonged intense rainfall
- Foundation design under service condition is acceptable
- Attention shall be given to brittle behaviour of concrete piles taking lateral load with rapid increase of wall pressure when rise of groundwater table within the wall.
- ▶ Need careful evaluation of design robustness of vertical or sub-vertical piles in taking lateral foundation loading
- ▶ Solutions :
 - ▶ Use more raked piles utilising more robust axial pile strength to resolve lateral imposed loading
 - ▶ Extra drainage capacity for temporary drains for large flat retained platform
 - ▶ Timely backfilling of suitable fill over granular fill of RS wall

68

29 December 2006 - Johor was the worst hit. Heavy rain – the highest recorded in 100 years – caused floods in Johor Baru and several major towns.



Lessons Learnt on Stability of a Piled Retaining Wall in Weak Soils

Ir. Liew Shaw-Shong




Content

- Chronological events
- Distress conditions of wall
- Desk study & subsurface conditions
- Forensic investigation (Geotechnical & Structural assessments)
- Probable Causations
- Remedial Solution
- Conclusion



Chronological events

- First SI : Jan 2005 (Within project site)
- Second SI : May 2005 (at wall area)
- Wall Distress : Feb 2006 (After prolonged rain)
- Forensic Investigation : Feb to Mar 2006



Tension Crack & Wall Distresses




Overall View of Site





Cross Section of Wall



Weephole Drains





Erosion by Weephole Discharge



Erosion of Wall Base






Aerial View (Pre-development)




Site Topography & SI Works






Previous 2-Stage Boreholes




Forensic Boreholes







Vane Shear Test Strength Profile




Stability Assessments





More prominent in effective stress analysis, but less for total stress analysis



Pile Integrity Testing





Pile Structural Assessments

- Rankine Pressure
- Brom's Lateral Pile Capacity:
 - Fixed Head : 32kN/pile (Likely the case)
 - Free Head : 20kN/pile
- Ultimate lateral pile capacity reached when $RL42.5m < GWT < RL45m$



Probable Causes of Wall Distress

- Potential perched water regime in natural valley terrain after raining
- Rise of groundwater increases the lateral force on wall
- Inadequate lateral pile resistance
- Reduction of effective soil strength due to reduction of vertical stress as wall loading carried by piles




Remedial Solution

- Soil Replacement for upper weak soil
- Overcut existing piles below new wall base
- Construct stabilising berm in front of new wall
- Provide subsoil drainage behind wall to control rise of groundwater seepage




Remedial Solution





Conclusion

- Potential perched water regime in natural valley terrain after raining
- Rise of groundwater (inefficient sub-terrain drainage) increases the lateral force on wall
- Inadequate lateral pile resistance
- Reduction of effective soil strength due to reduction of vertical stress as wall loading carried by piles
- Slender vertical piles not suitable for supporting wall on weak & compressible soils (Poor lateral resistance)
- Remedial works : Soil Replacement + Subsoil drainage + Stabilising berm
- Solution : Raked piles in combination of vertical piles (Serviceability limit state)



Thank You

